

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010547/KES3Q2

Date: 13/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070054141
Claimant		
Vehicle No : SLV6253P	Insured Vehicle No :	SMS9563D
Date of Loss: 30/09/2020	Nature of Claim: TP	Claim No: 2495456535SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV6253P	Engine No:	3A92UGN6889
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AJH000854
Reg. Date:	09/01/2018 (Man. Year: 2017)	Odometer:	14016 km
Colour:	Metallic Red		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,937.20	2,584.80	352.40	12.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,330.00	1,720.00	610.00	26.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,267.20	4,304.80	962.40	18.27
Approved Total (Overridden) (S\$)		3,450.00		
Nett Amount (S\$)	5,267.20	3,450.00	1,817.20	34.50
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,757.45		

INSPECTION

Date of Assignment:	01/10/2020	
Date Inspected:	05/10/2020 Inspected At:	Hwa Seng Spray Painting Co (160 SIN MING) 160 SIN MING DRIVE, #05-11 SIN MING AUTOCITY Singapore 575722
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT REAR DOOR	Bent	1,009.00 FL	*1,009.00 FL
2	1		*RIGHT REAR PANEL	Bent	823.00 FL	*823.00 FL
3	1		*RIGHT REAR INNER SHIELD	Serviceable	55.00 FL	* - FL
4	1		*RIGHT REAR DOOR RUBBER	Serviceable	181.00 FL	* - FL
5	1		*RIGHT REAR SPORT RIM	Dented	285.00 FL	*285.00 FL
6	1		*REAR BUMPER	Mtg Cracked	708.00 FL	*608.00 FL
7	1		*DOOR STICKER	Necessary	47.00 FL	*47.00 FL
8	1		*SEALANT & CLIP	Necessary	80.00 FS	*60.00 FS
9	1		*INNER SEAL	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,248.00	2,862.00
- List Item Discount on L Items 10.00/10.00% (S\$)	310.80	277.20
Total Parts (S\$)	2,937.20	2,584.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL KNOCKING	New	900.00	800.00
2	SPRAY PAINTING	New	1,000.00	660.00
3	WIRE CHECKING	New	50.00	20.00
4	LABOUR TO REMOVE & INSTALL REAR WINDSCREEN	New	160.00	120.00
5	LABOUR TO TRANSFER DOOR TRIM & ATTACH PART	New	100.00	60.00
6	COMPUTERISED WHEEL ALIGNMENT	New	120.00	60.00
			Gross Labour Cost (\$)	1,720.00
			2,330.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >