

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR19011312/UPS3Q2-1

Date: 21/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994777

Claimant
Vehicle No : FX6299T **Insured Vehicle No :** SLK3975S

Date of Loss: 24/03/2018 Nature of Claim: TP Claim No: 7108453368SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FX6299T		
Make & Model:	PIAGGIO X9 200, 198cc EVO (A)	Engine No:	ZAPM2300004010483
Reg. Date:	19/01/2004 (Man. Year: 2003)	Chassis No:	M236M11560
Colour:	Grey	Odometer:	0 km
Engine Capacity:	198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70-14	Rear Tyre Size:	140/60-14
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 0 mm	Rear Right Side:	Pirelli 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,635.20	3,919.60	3,715.60	48.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	505.00	385.00	120.00	23.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,140.20	4,304.60	3,835.60	47.12
Approved Total (Overridden) (\$\$)		3,400.00		
Nett Amount (\$\$)	8,140.20	3,400.00	4,740.20	58.23
+ Loss of Use (6.0 x S\$20.00/day) (\$\$)		120.00		
Nett Liability (\$\$)		3,520.00		

INSPECTION

Date of Assignment: 25/06/2019

Date Inspected: 26/06/2019 Inspected At:

Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
1 Kaki Bukit Avenue 6, #02-62
AutoBay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Repair	175.00 FL	*- FL
2	1		*FRONT FAIRING	Cracked	280.00 FL	*280.00 FL
3	1		*FRONT FAIRING INNER PANEL	Cracked	185.00 FL	*185.00 FL
4	1		*WINDSHIELD -UPPER	Broken	135.00 FL	*135.00 FL
5	1		*WINDSHIELD (LOWER)	Broken	220.00 FL	*220.00 FL
6	1		*TOP INNER PANEL	Cracked	88.00 FL	*88.00 FL
7	1		*COMPARTMENT COVER	Cracked	85.00 FL	*85.00 FL
8	1		*SIDE MIRRORS	O/S Broken	570.00 FL	*265.00 FL
9	1		*FRONT FORK ASSY	Repair	750.00 FL	*- FL
10	1		*FORK UNDER BRACKET	Not Necessary	175.00 FL	*- FL
11	1		*FRONT SPORT RIM	Dented	335.00 FL	*335.00 FL
12	1		*FRONT BRAKE DISC	Not Necessary	195.00 FL	*- FL
13	1		*HANDLE -BAR	Bent	110.00 FL	*110.00 FL
14	1		*HANDLE -BAR BALANCER	O/S Scratched	160.00 FL	*80.00 FL
15	1		*BRAKE LEVER	Not Necessary	48.00 FL	*- FL
16	1		*HEADLAMP	Cracked	310.00 FL	*310.00 FL
17	1		*FRONT FAIRING BRACKET	Bent	285.00 FL	*285.00 FL
18	1		*SIDE COWLING	Cracked	280.00 FL	*280.00 FL
19	1		*SIDE LOWER PANEL	Cracked	120.00 FL	*120.00 FL
20	1		*LOWER BELLY COWLING	Cut	195.00 FL	*195.00 FL
21	1		*CENTRE INNER PANEL	Cracked	135.00 FL	*135.00 FL
22	1		*FOOTSTEP PANELS	O/S Cut	256.00 FL	*125.00 FL
23	1		*FOOTSTEP RUBBERS	O/S Torn	90.00 FL	*45.00 FL
24	1		*REAR SIDE PANELS	O/S Cracked	180.00 FL	*90.00 FL
25	1		*REAR END PANEL	Bent	88.00 FL	*88.00 FL
26	1		*REAR TAILBOARDS	O/S Cracked	520.00 FL	*260.00 FL
27	1		*REAR TAILLAMP	Not Necessary	180.00 FL	*- FL
28	1		*REAR FENDER	Not Necessary	165.00 FL	*- FL
29	1		*SIDE STAND	Not Necessary	115.00 FL	*- FL
30	1		*MAIN STAND	Not Necessary	180.00 FL	*- FL
31	1		*ENGINE MOUNTING BRACKET	Repair	280.00 FL	*- FL
32	1		*EXHAUST	Repair	460.00 FL	*- FL
33	1		*EXHAUST PROTECTOR	Scratched	48.00 FL	*48.00 FL
34	1		*REAR BOX	Missing	500.00 FL	*300.00 FL
35	1		*SET REAR BOX BRACKET	Cracked	280.00 FL	*280.00 FL
36	1		*SET NUMBER PLATE	Necessary	28.00 FS	*10.00 FS
37	2		*FORK OILS	Not Necessary	60.00 FS	*- FS
38	2		*FORK OIL SEALS	Not Necessary	112.00 FS	*- FS
39	1		*SET STEERING CONE	Not Necessary	75.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,453.00	4,354.00
- List Item Discount on L Items 10.00/10.00% (\$)	817.80	434.40
Total Parts (\$)	7,635.20	3,919.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE	New	45.00	35.00
2	TO PROVIDE LABOUR	New	380.00	350.00
3	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
Gross Labour Cost (\$\$)			505.00	385.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >