

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20010557/NYD3E2

Date: 29/12/2020

REFERENCE

Insured/Claimant: LAM KAR YAN Policy No: 1800062519
Date of Loss: 30/09/2020 Nature of Claim: OD Claim No: 8865664469SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBM9517A**
Make & Model: YAMAHA XMAX 300, 292cc Engine No: H336E0031485
Reg. Date: 26/05/2018 (Man. Year: 2018) Chassis No: MH3SH0846JK003811
Colour: Grey Odometer: 23712 km
Engine Capacity: 292 cc
Market Value/New Car Price: S\$15,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 120/70 R15 Rear Tyre Size: 140/70 R14
Front Left Side: Dunlop 3 mm Rear Left Side: Bridgestone 4 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,418.50	3,185.50	3,233.00	50.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,080.00	840.00	1,240.00	59.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,498.50	4,025.50	4,473.00	52.63
Approved Total (Overridden) (S\$)		3,200.00		
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	8,198.50	2,900.00	5,298.50	64.63
+ GST 7.00/7.00% (S\$)	573.90	203.00	370.90	64.63
Nett Amount (S\$)	8,772.40	3,103.00	5,669.40	64.63

INSPECTION

Date of Assignment: 05/10/2020
Date Inspected: 02/10/2020 Inspected At: Bike Production Pte Ltd (HQ)
610 SERANGOON ROAD
Singapore 218216
Estimated Period of Repair: 3.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT MUDGUARD	Cracked	140.00 FL	*140.00 FL
2	1		*FRONT MUDGUARD RIGHT	Cracked	110.00 FL	*110.00 FL
3	1		*RIGHT FRONT FORK	Not Necessary	780.00 FL	*- FL
4	1		*LEFT FRONT FORK	Serviceable	780.00 FL	*- FL
5	1		*FRONT WHEEL SHAFT	Serviceable	95.00 FL	*- FL
6	1		*FRONT BRAKE DISK	Serviceable	275.00 FL	*- FL
7	1		*STEERING STEM	Deformed	255.00 FL	*255.00 FL
8	2		*STEERING STEM BEARINGS	Necessary	90.00 FL	*90.00 FL
9	1		*HEADLAMP ASSY	Cracked	395.00 FL	*395.00 FL
10	1		*BLACK FRONT UPPER COVER	Scratched	315.00 FL	*315.00 FL
11	1		*BLACK FRONT LOWER COVER	Cracked	245.00 FL	*245.00 FL
12	1		*RIGHT FAIRING	Scratched	325.00 FL	*325.00 FL
13	1		*RIGHT VIEW MIRROR	Serviceable	140.00 FL	*- FL
14	1		*LOWER RIGHT COVER	Scratched	185.00 FL	*185.00 FL
15	1		*RIGHT FOOTSTEP	Scratched	295.00 FL	*295.00 FL
16	1		*EXHAUST CONNECTOR	Necessary	75.00 FL	*75.00 FL
17	1		*EXHAUST ASSEMBLY	Repair	750.00 FL	*- FL
18	1		*FRONT TYRE	Serviceable	145.00 FS	*- FS
19	1		*FRONT SPORT RIM	Serviceable	550.00 FS	*- FS
20	1		*YAMAHA AMBLEM	Necessary	50.00 FL	*50.00 FL
21	1		*RADIATOR GUARD	Cracked	125.00 FL	*125.00 FL
22	1		*BELLY PAN	Scratched	110.00 FL	*110.00 FL
23	1		*REAR FOOTREST	Scratched	75.00 FL	*75.00 FL
24	1		*EXHAUST PROTECTOR	Scratched	135.00 FL	*135.00 FL
25	1		*RIGHT BLACK COVER	Cracked	135.00 FL	*135.00 FL
26	1		*RIGHT FRONT SIGNAL	Cracked	140.00 FL	*140.00 FL
27	1		*REAR EXHAUST COVER	Scratched	95.00 FL	*95.00 FL
28	1		*REAR BOX	Broken	220.00 FS	*220.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,030.00	3,515.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	611.50	329.50
Total Parts (\$\$)	6,418.50	3,185.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	100.00	0.00
2	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS, CHECK WIRING AND LIGHTING SYSTEM	New	700.00	450.00
3	TO REPLACE AND BALANCE FRONT WHEEL RIM	New	150.00	0.00
4	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING	New	380.00	0.00
5	SPRAY PAINTING	New	350.00	200.00
6	RESET METER	New	120.00	0.00
7	TO REPLACE AND REFIT AND ALIGN FRONT FORKS	New	180.00	90.00
8	REPAIR EXHAUST	New	100.00	100.00
			Gross Labour Cost (S\$)	2,080.00
				840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >