

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20010558/UPS3Q2

**Date:** 03/11/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SKN4886E	<b>Insured Vehicle No :</b>	SHD3854S
Date of Loss: 29/09/2020	Nature of Claim: TP	Claim No: MCT20090461

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN4886E		
Make & Model:	MAZDA 6, 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A)	Engine No:	PE20496218
Reg. Date:	20/06/2014 (Man. Year: 2014)	Chassis No:	JM6GJ1071E0136979
Colour:	Silver	Odometer:	114575 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,656.08	1,801.20	854.88	32.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	900.00	500.00	35.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>4,056.08</b>	<b>2,701.20</b>	<b>1,354.88</b>	<b>33.40</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,150.00</b>		
<b>Nett Amount (\$\$)</b>	<b>4,056.08</b>	<b>2,150.00</b>	<b>1,906.08</b>	<b>46.99</b>
<b>+ Loss of Use (3.0 x S\$100.00/day) (\$\$)</b>		300.00		
	<b>Nett Liability (\$\$)</b>	<b>2,450.00</b>		

### INSPECTION

Date of Assignment:	01/10/2020	
Date Inspected:	05/10/2020 Inspected At:	Soc Leon Motor Works (Kaki Bukit) 1 Kaki Bukit Ave 6, #01-91, AutoBay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	3.0 days	

**Adjuster:** MARCUS CHUA

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 08 Oct 2020)
<b>Parts:</b>	143	MAZDA 6 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKN4886E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*REAR BUMPER</b>	Dented / Deformed	1,290.00 FL	*1,206.20 FL
2	2		<b>*CENTRE REVERSE SENSOR</b>	Shorted	460.00 FL	*407.20 FL
3	1		<b>*REAR BUMPER REINFORCEMENT</b>	Dented	620.00 FL	*538.30 FL
4	1		<b>*SET BUMPER CLIPS</b>	Necessary	80.00 FL	*50.00 FL
5	2		<b>*BUMPER SIDE RETAINER</b>	Not Necessary	90.00 FL	*- FL
6	2		<b>*TOWING COVER</b>	Deformed	80.00 FL	*49.80 FL
7	1		<b>*REAR END PANEL</b>	Repair	700.10 FL	*- FL
					<b>Sub Total (S\$)</b>	<b>3,320.10 2,251.50</b>
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>664.02 450.30</b>
					<b>Total Parts (S\$)</b>	<b>2,656.08 1,801.20</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO SPRAY ANTI-RUST	New	100.00	0.00
2	LABOUR CHARGE FOR KNOCKING & REPALCING PARTS	New	600.00	400.00
3	SPRAYPAINTING	New	700.00	500.00
<b>Gross Labour Cost (S\$)</b>			<b>1,400.00</b>	<b>900.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >