

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20010564/ARS3Q2

Date: 27/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SLQ3347Z **Insured Vehicle No :** GBG467B

Date of Loss: 29/09/2020 Nature of Claim: TP Claim No: 5030198513SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ3347Z	Engine No:	L15B3597589
Make & Model:	HONDA STEPWAGON SPADA, 1.5 (A)	Chassis No:	RP31022054
Reg. Date:	04/07/2017 (Man. Year: 2015)	Odometer:	83940 km
Colour:	Purple		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,823.36	6,282.00	4,541.36	41.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,690.00	2,110.00	580.00	21.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,513.36	8,392.00	5,121.36	37.90
Approved Total (Overridden) (S\$)		6,700.00		
(S\$)	13,513.36	6,700.00	6,813.36	50.42
+ GST 7.00/7.00% (S\$)	945.94	469.00	476.94	50.42
Nett Amount (S\$)	14,459.30	7,169.00	7,290.30	50.42
+ Car Rental (7.0 x S\$85.00/day) (S\$)		595.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,766.00		

INSPECTION

Date of Assignment: 30/09/2020

Date Inspected: 30/09/2020 Inspected At:

Lee Sheng Auto Pte Ltd (HQ)
1 Kaki Bukit Avenue 6, #01-58/60
AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	785.20 FL	*- FL
2	1		*HEAD LAMP LH	Cracked	1,950.40 FL	*1,950.40 FL
3	1		*GRILLE BASE	Not Necessary	368.40 FL	*- FL
4	1		*GRILLE CHROME	Not Necessary	368.40 FL	*- FL
5	1		*GRILLE CHROME LOWER	Not Necessary	149.20 FL	*- FL
6	1		*FRONT BUMPER	Distorted	958.20 FL	*958.20 FL
7	1		*FRONT BUMPER RETAINER LH	Damaged	20.40 FL	*20.40 FL
8	1		*HEADLAMP BRACKET	Cracked	36.50 FL	*36.50 FL
9	1		*FRONT FENDER LH	Dented	637.00 FL	*637.00 FL
10	1		*FRONT FENDER LINER LH	Torn	120.40 FL	*120.40 FL
11	2		*FRONT FENDER CLIPS	Necessary	11.00 FL	*11.00 FL
12	2		*GRILLE CLIP	Not Necessary	11.00 FL	*- FL
13	10		*FRONT BUMPER CLIPS	Necessary	55.00 FL	*30.00 FL
14	1		*FOG LAMP LH	Cracked	275.60 FL	*275.60 FL
15	1		*FOG LAMP COVER LH	Cracked	149.00 FL	*149.00 FL
16	1		*SIDE MIRROR COVER LH	Not Necessary	189.40 FL	*- FL
17	1		*FRONT DOOR LH	Repair	971.10 FL	*- FL
18	1		*REAR DOOR L/H	Dented	985.40 FL	*985.40 FL
19	1		*WASHER TANK	Not Necessary	79.20 FL	*- FL
20	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	330.20 FL	*- FL
21	1		*FOG LAMP COVER CHROME LH	Cracked	554.20 FL	*125.00 FL
22	1		*FENDER EXTENSION FRT/LH	Bent	310.00 FL	*310.00 FL
23	1		*FENDER CHASSIS GUSSET LH	Repair	410.00 FL	*- FL
24	1		*WHEEL RIM LH	Cut	788.32 FS	*500.00 FS
25	1		*FRONT SHOCK ABSORBER LH	Bent	389.40 FL	*389.40 FL
26	1		*FRONT LOWER ARM LH	Bent	325.90 FL	*325.90 FL
27	1		*FRONT KNUCKLE ARM LH	Damaged	410.40 FL	*410.40 FL
28	1		*FRONT KNUCKLE ARM BEARING LH	Damaged	142.90 FL	*142.90 FL
29	1		*FRONT BUMPER LOWER LIP	Not Necessary	380.00 FS	*- FS
30	1		*FRONT BUMPER SIDE LIP	Cracked	280.00 FS	*280.00 FS
31	1		*ROCKER GARNISH LOWER LIP LH	Not Necessary	380.00 FS	*- FS
32	1		*WHEEL TYRE	Not Necessary	150.00 FS	*- FS
33	1		*FRONT NUMBER PLATE & BASE	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,022.12	7,657.50
- List Item Discount on L Items 20.00/20.00% (\$)	2,198.76	1,375.50
Total Parts (\$)	10,823.36	6,282.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	KNOCKING ,CUTTING ,JACKING WELDING ETC	New	1,000.00	800.00
2	SPRAY PAINTING	New	1,000.00	900.00
3	REMOVE & REFIX UNDERCARRIAGE	New	250.00	220.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	30.00
5	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	80.00
6	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	200.00	80.00
			Gross Labour Cost (\$)	2,690.00
				2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >