

ASS. REC. BY:

REF:

AXA/20010307/K623

C

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

851K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

G13J 4198K

Yr Regn:

04, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS

NV200

c.c

1461

Colour:

D. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading:

34077

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VSK YBAM208 0176766

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

175/70R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

28/9/20

D.O.I.

2/10/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 GIA &amp; EG not ready

13/10 8342455 343455 Confirmed

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S - RS - SI

FURTHER

OTHERS

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$

# LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645  
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721  
 Tel No. : 64534177 Fax No. : 64593724  
 E-Mail : limyewboo@singnet.com.sg  
 Website : www.limyewboo.com.sg  
 Buss. Reg. No. : 200514/00L

email Kenneth  
 on 5/10/2020

sms Kenneth on 9/10/2020

AXA INSURANCE SINGAPORE PTE LTD  
 8 SHENTON WAY #27-01  
 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department

Contact : 63387288 Fax No. : 68804838

Not Notwithstanding  
 Penney B4 paint

83434.55

Estimate : TP20/035

Date : 05/10/2020  
 Vehicle Num. : GBJ 4198K  
 Make/Model : NISSAN NV200-2019  
 Chassis/Eng# : VSKYBAM20Z0176766/K9KE628D656991  
 Accident Date : 30/09/2020  
 Claim No. :  
 Reference : LYB/GBJ4198K/AXA/tp/sl  
 Policy No. : (14/04/2021)

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

|     |   |                            |  |  |
|-----|---|----------------------------|--|--|
| 1.  | 1 | NETT ITEMS :               |  |  |
| 2.  | 1 | REAR TAILGATE              |  |  |
| 3.  | 1 | REAR TAILGATE WEATHERSTRIP |  |  |
| 4.  | 1 | REAR TAILGATE HINGE-LOWER  |  |  |
| 5.  | 1 | REAR TAILLAMP/LH           |  |  |
| 6.  | 1 | REAR EMBLEM 'NISSAN' LOGO  |  |  |
| 7.  | 1 | REAR EMBLEM 'NV 200'       |  |  |
| 8.  | 2 | REAR BUMPER                |  |  |
| 9.  | 1 | REAR BUMPER RETAINER       |  |  |
| 10. | 1 | REAR BUMPER SPONGE         |  |  |
|     |   | REAR NO PLATE              |  |  |

Nett Total S\$ :

10.00% Discount S\$ :

SPECIAL NETT ITEMS :

|    |       |                          |
|----|-------|--------------------------|
| 1. | 1     | REAR '70 KM/H' STICKER   |
| 2. | 1     | REAR '6 PAX' STICKER     |
| 3. | 1     | REAR NO PLATE HOLDER     |
| 4. | 1     | REAR W/SCREEN SEALANT    |
| 5. | 1     | REAR W/SCREEN INNER SEAL |
| 6. | 1 SET | REAR REVERSE SENSOR      |

Special Nett Total S\$ :

|          |   |
|----------|---|
| 1,381.10 | ✓ |
| 96.40    | X |
| 119.90   | X |
| 258.70   | ✓ |
| 87.00    | ✓ |
| 59.70    | ✓ |
| 740.00   | ✓ |
| 110.00   | X |
| 84.00    | X |
| 35.00    | X |
| 2,971.80 |   |
| 297.18   |   |
| 2,674.62 |   |

|        |       |
|--------|-------|
| 12.00  | ✓     |
| 12.00  | X     |
| 25.00  | X     |
| 40.00  | ✓     |
| 40.00  | ✓     |
| 250.00 | X     |
| 379.00 | 2001- |

CONTINUE / ...

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645  
NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721

Tel No. : 64534177 Fax No. : 64593724

E-Mail : limyewboo@singnet.com.sg

Website : www.limyewboo.com.sg

Buss. Reg. No. : 200514/00L

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY #27-01

AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department

Contact : 63387288 Fax No. : 68804838

Estimate : TP20/035

Date : 05/10/2020

Vehicle Num. : GBJ 4198K

Make/Model : NISSAN NV200-2019

Chassis/Eng# : VSKYBAM20Z0176766/K9KE628D656991

Accident Date : 30/09/2020

Claim No. :

Reference : LYB/GBJ4198K/AXA/tp/sl

Policy No. : (14/04/2021)

| S/N | Quantity | Particular                                                                                                                             | Unit Price | Amount S\$ |
|-----|----------|----------------------------------------------------------------------------------------------------------------------------------------|------------|------------|
|     |          | LABOUR :                                                                                                                               |            |            |
|     |          | TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS                                                                                    | 120.00     | 300        |
|     |          | LABOUR TO REMOVE & REFIX REAR W/SCREEN                                                                                                 | 150.00     | 600        |
|     |          | TO CHECK WATER SEEPAGE                                                                                                                 | 60.00      | 200        |
|     |          | LABOUR TO REPLACE THE SENSOR & CHECK WIRING FUNCTIONS                                                                                  | 80.00      | 500        |
|     |          | TO CHECK,REPAIR, ALIGN ON REAR AFFECTED EXHAUST                                                                                        | 120.00     | X          |
|     |          | TO REMOVE & REFIX REAR CAMERA WITH NEW SEALANT TAPE<br>IN ORDER TO FACILIATE REPAIR JOB                                                | 60.00      | 500        |
|     |          | TO REPAIR, PANEL BEAT, ALIGN ON REAR END PANEL,AFFECTED<br>RIGHT REAR TAILGATE & LABOUR TO REPLACE ABOVE PARTS                         | 800.00     | 5000       |
|     |          | TO PRIMER,PUTTY & SPRAY PAINT ON REAR LEFT NEW TAILGATE<br>REAR END PANEL & TOUCH UP ON REAR AFFECTED RIGHT<br>TAILGATE USING 2K PAINT | 800.00     | 4000       |
|     |          | Labour Total S\$ :                                                                                                                     |            | 2,190.00   |



E. & O.E.

Total S\$ : 5,243.62

=====

for LIM YEW BOO SPRAY PAINT CO.