



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax : +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	SLC7275U
Policy No:	DMHCSNA00004172001	Date of Loss:	22/09/2020
Vehicle Reg. No.:	SLC7275U	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	RENO5 GENERAL SERVICE	Contact No:	+6590298310
Make/Model:	TOYOTA WISH, 1.8 (A)	Vehicle Reg. Date:	21/07/2006
Vehicle Colour:	Silver	Gen Condition:	Good
Engine No:	1ZZ2623780	Chassis No:	ZNE100315287
Odometer:	402091 KM		

Paint Type:

Total Loss? **YES**

Est. Duration of Repair (day) 28

Present Location: GOLDBELL ENGINEERING PTE LTD (TUAS)

COST OF CLAIMS	Amount
Parts	0.00
Miscellaneous Items	0.00
Labour	5,000.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	5,000.00
+ GST 7.00% (\$\$)	350.00
Nett Amount (\$\$)	5,350.00

This claim is handled by: SOO LEONG KEAT

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Sep 2020)

Parts: M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Goldbell Engineering Pte Ltd/SLC7275U/30/09/2020 10:50

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET	0.00	0.00	-
2	1		*FRONT BONNET LOCK	0.00	0.00	-
3	1		*FRONT BONNET LOCK HATCH	0.00	0.00	-
4	1		*FRONT BONNET HINGE LH	0.00	0.00	-
5	1		*FRONT BONNET HINGE RH	0.00	0.00	-
6	1		*FRONT FENDER LH	0.00	0.00	-
7	1		*FRONT FENDER RH	0.00	0.00	-
8	1		*FRONT WHEEL HOUSING LH	0.00	0.00	-
9	1		*FRONT WHEEL HOUSING CLIP	0.00	0.00	-
10	1		*FRONT BUMPER	0.00	0.00	-
11	1		*FRONT BUMPER CLIP	0.00	0.00	-
12	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	-
13	1		*FRONT BUMPER BRACKET LH	0.00	0.00	-
14	1		*FRONT BUMPER BRACKET RH	0.00	0.00	-
15	1		*FRONT BUMPER INNER FOAM	0.00	0.00	-
16	1		*FRONT PANEL	0.00	0.00	-
17	1		*FRONT BUMPER GRILLE	0.00	0.00	-
18	1		*FRONT FOGLAMP LH	0.00	0.00	-
19	1		*FRONT FOGLAMP RH	0.00	0.00	-
20	1		*FRONT HEADLAMP LH	0.00	0.00	-
21	1		*FRONT HEADLAMP RH	0.00	0.00	-
22	1		*FRONT AIR CON CONDENSOR	0.00	0.00	-
23	1		*FRONT RADIATOR	0.00	0.00	-
24	1		*FRONT WINDSCREEN	0.00	0.00	-
Total Parts (\$\$)						0.00

Goldbell Engineering Pte Ltd/SLC7275U/30/09/2020 10:50. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	COOLANT	-
2	1	ECU BRACKET	-
3	1	FRONT BONNET CHROME	-
4	2	FRONT BUMPER SENSOR	-
5	1	FRONT NUMBER PLATE	-
6	1	FRONT NUMBER PLATE HOLDER	-
7	1	FRONT WINDSCREEN MOULDING	-
8	2	FRONT WINDSCREEN SEALANT	-
9	2	HORN	-
10	1	TOYOTA WISH LOGO	-
Sub Total (\$\$)			0.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	SPRAY PAINT ON THE AFFECTED DAMAGED PARTS.	New	-
Labour Items			
2	LABOUR TO REPLACE , TO PANEL BEAT & TO REPAIR ON THE AFFECTED DAMAGED PARTS.	New	5,000.00
3	WIRING	New	-
4	TO REMOVE & REFIT FRONT WINDSCREEN	New	-
5	TOP UP AIR CON GAS	New	-
Gross Labour Cost (\$\$)			5,000.00

Goldbell Engineering Pte Ltd/SLC7275U/30/09/2020 10:50. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

