

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFZ 9467U**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	DISTORTED	1,886.50	1,215.32
1	FRONT BUMPER REINFORCEMENT	DENTED	655.20	388.20
1	FRONT BUMPER SIDE RETAINER O/S	CRACKED	82.80	65.50
1	FRONT BUMPER NOZZLE COVER	TORN	45.00	45.00
1	FRONT BUMPER NOZZLE	CRACKED	288.20	288.20
1	FRONT BUMPER FOG LAMP O/S	CRACKED	450.50	450.50
1	FRONT BUMPER PDC SENSOR O/S	SHORTED	235.00	199.00
1	FRONT BUMPER INNER RETAINER O/S	CRACKED	188.20	188.20
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	HEADLAMP O/S	HOLDER CRACKED	2,880.20	2,180.00
1	FRONT FENDER O/S	TO REPAIR SEE LABOUR	661.30	-
1	FRONT FENDER INNERSHIELD O/S	NOT NECESSARY	199.50	-
1	SET FRONT FENDER INNERSHIELD CLIPS O/S	NOT NECESSARY	50.00	-
	LESS 10% DISCOUNT		-	-506.99
			7,672.40	4,562.93
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER O/S.		800.00	280.00
	TO PUTTY & SPRAY PAINTING.		800.00	400.00
			1,780.00	700.00
	<b>GRAND TOTAL</b>		<b>9,452.40</b>	<b>5,262.93</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,200.00</b>

Report Ref No. CS/SMO20010577/Uyd3e2

**CHUA KANG SENG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.