

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20010595/AQF3Q2

Date: 01/02/2021

REFERENCE

Insured/Claimant: ROCKY YULIANTO SAPUTRA

Policy No: 1900020101

Date of Loss: 30/09/2020

Nature of Claim: OD

Claim No: 4394588051SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMJ3626T**

Make & Model: AUDI A3 SPORTBACK, 999cc TFSI S TRONIC (LED) (A)

Engine No: CHZC26035

Reg. Date: 28/02/2019 (Man. Year: 2018)

Chassis No: WAUZZZ8VOKAO28716

Colour: Black

Odometer: 21285 km

Engine Capacity: 999 cc

Market Value/New Car Price: S\$94,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,189.00	2,969.28	15,219.72	83.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,572.00	1,522.00	1,050.00	40.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,761.00	4,491.28	16,269.72	78.37
+ GST 7.00/7.00% (S\$)	1,453.27	314.39	1,138.88	78.37
Nett Amount (S\$)	22,214.27	4,805.67	17,408.60	78.37

INSPECTION

Date of Assignment: 02/10/2020

Date Inspected: 02/10/2020 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,842.00 FS	*1,473.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	185.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	76.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Cracked	159.00 FS	*126.80 FS
5	1		*FRONT BUMPER GRILLE CLOSING ELEMENT - LOWER CENTRE	Not Necessary	293.00 FS	*- FS
6	2		*FRONT BUMPER CLOSING ELEMENT- LH / RH	Not Necessary	586.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,406.00 FS	*1,124.80 FS
8	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	189.00 FS	*- FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	N/S Cracked	372.00 FS	*148.40 FS
10	1		*FRONT REINFORCEMENT BEAM	Not Necessary	715.00 FS	*- FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	187.00 FS	*- FS
12	1		*FOAM FILLER PIECE COVER	Not Necessary	121.00 FS	*- FS
13	1		*AIRCON STICKER	Necessary	8.00 FS	*5.68 FS
14	1		*CAUTION SIGN STICKER	Necessary	14.00 FS	*10.80 FS
15	1		*SIGNAL HORN - LH HIGH TONE	Not Necessary	197.00 FS	*- FS
16	1		*SIGNAL HORN - RH LOW TONE	Not Necessary	197.00 FS	*- FS
17	2		*LED HEADLIGHT - LH / RH	Not Necessary	10,910.00 FS	*- FS
18	2		*LIFT CYLINDER - LH / RH	Not Necessary	282.00 FS	*- FS
19	1		*LIFT CYLINDER HOSE	Not Necessary	67.00 FS	*- FS
20	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	48.00 FS	*- FS
21	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Not Necessary	12.00 FS	*- FS
22	1		*BONNET CATCH HOOK	Not Necessary	63.00 FS	*- FS
23	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
24	1		*SUNDRIES	Necessary	200.00 FS	*19.20 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 18,189.00 2,969.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	New	280.00	280.00
2	TO DISMANTLE AND RENEW FRONT BUMPER. REORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED.	New	1,000.00	500.00
3	TO RESPRAY FRONT BUMPER.	New	1,100.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (\$\$)			2,572.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >