

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 9362S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (SN)	DEFORMED	1,128.60	1,128.60
1	BRACKET CENTER (SN)	SERVICEABLE	5.40	-
4	GROMMET, REAR BUMPER (SN)	NECESSARY	10.80	10.80
4	RIVET, REAR BUMPER (SN)	NECESSARY	18.00	18.00
4	FASTENER, REAR BUMPER (SN)	NECESSARY	12.00	12.00
2	CLIP, REAR BUMPER (SN)	NECESSARY	6.80	6.80
4	CLIP, REAR BUMPER (SN)	NECESSARY	14.80	14.80
2	RETAINER CENTER, SENSOR (SN)	SERVICEABLE	36.40	-
2	SENSOR CENTER, ULTRASONIC (SN)	SERVICEABLE	407.20	-
3	TAPE PROTECTOR, REAR BUMPER (SN)	NECESSARY	25.80	25.80
1	REAR REINFORMENT (SN)	BENT	564.20	564.20
1	GASKET LHS, TAILLAMP (SN)	NECESSARY	22.00	22.00
1	GASKET RHS, TAILLAMP (SN)	NECESSARY	22.00	22.00
1	ANTENNA (SN)	SERVICEABLE	111.10	-
1	CLIP, ANTENNA (SN)	NOT NECESSARY	2.70	-
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			2,487.80	1,845.00
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT, REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		1,650.00	660.00
	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.		1,575.00	630.00
	TO TRANSFER REVERSE SENSOR.		330.00	280.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	250.00	-
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	180.00
			4,405.00	1,900.00
	GRAND TOTAL		6,892.80	3,745.00

Report Ref No. CS/GAI20010603/R1qf3e2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 3,745.00

Report Ref No. CS/GAI20010603/R1qf3e2

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

X.S.

**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

**Licensed Appraiser**