

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20010610/DBA3Q2
Date: 28/05/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SHA4778M	Insured Vehicle No :	SHD3404H
Date of Loss:	01/10/2020	Nature of Claim:	TP
		Claim No:	MCT20100016

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA4778M	Engine No:	G4LEJU076112
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Chassis No:	KMHC851CVKU106498
Reg. Date:	10/08/2018 (Man. Year: 2018)	Odometer:	251586 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 5 mm	Rear Left Side:	Davanti 5 mm
Front Right Side:	Davanti 5 mm	Rear Right Side:	Davanti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,004.60	6,071.84	4,932.76	44.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,730.00	1,490.00	3,240.00	68.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,734.60	7,561.84	8,172.76	51.94
+ GST 7.00/7.00% (S\$)	1,101.42	529.33	572.09	51.94

Nett Amount (S\$)	16,836.02	8,091.17	8,744.85	51.94
+ Loss of Use (8.0 x S\$40.00/day) (S\$)		320.00		
+ Car Rental (8.0 x S\$125.19/day) (S\$)		1,001.52		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		9,492.69		

INSPECTION

Date of Assignment: 02/10/2020

Date Inspected: 05/10/2020

Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
 Blk 9 Sector C #01-42 Sin Ming Industrial Estate
 Singapore 575644

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Apr 2021)		
Parts:	N/A	HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SHA4778M)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR (RH)	Bent	1,789.90 FL	*1,789.90 FL
2	1		*REAR DOOR TRIM BOARD (RH)	Not Necessary	613.60 FL	*- FL
3	1		*REAR DOOR PROTECTOR (RH)	Not Necessary	166.20 FL	*- FL
4	1		*REAR FENDER (RH)	Dented	1,768.30 FL	*1,768.30 FL
5	1		*REAR FENDER SHIELD FRT PIECE (RH)	Not Necessary	165.50 FL	*- FL
6	1		*REAR FENDER AIR-DUCT (RH)	Not Necessary	87.30 FL	*- FL
7	1		*REAR FENDER TRIM BOARD (RH)	Not Necessary	788.75 FL	*- FL
8	1		*ASSY BSD BLIND SPOT RADAR (RH)	Not Necessary	1,625.00 FL	*- FL
9	1		*REAR TYRE RIM (RH)	Distorted	1,124.20 FL	*1,124.20 FL
10	1		*REAR WHEEL HUP-CAP (RH)	Cut	346.40 FL	*346.40 FL
11	1		*REAR WHEELBEARING & HUB ASSY	Damaged	554.00 FL	*554.00 FL
12	1		*REAR TRAILING ARM (RH)	Distorted	265.40 FL	*265.40 FL
13	1		*REAR ASSIST (RH)	Distorted	227.90 FL	*227.90 FL
14	1		*REAR SHOCK ABSORBER (RH)	Distorted	230.50 FL	*230.50 FL
15	1		*REAR SHOCK ABSORBER MOUNTING (RH)	Not Necessary	133.10 FL	*- FL
16	1		*REAR ABSORBER STOPPER (RH)	Not Necessary	137.60 FL	*- FL
17	1		*REAR ABSORBER COVER (RH)	Not Necessary	175.60 FL	*- FL
18	1		*REAR CROSSMEMBER	Not Necessary	1,468.70 FL	*- FL
19	1		*STABILIZER BAR	Not Necessary	387.30 FL	*- FL
20	1		*STABILIZER LINK (RH)	Not Necessary	147.30 FL	*- FL
21	1		*REAR UPPER ARM (RH)	Distorted	239.50 FL	*239.50 FL
22	1		*REAR LOWER ARM (RH)	Distorted	393.10 FL	*393.10 FL
23	1		*REAR KNUCKLE ARM (RH)	Distorted	538.10 FL	*538.10 FL
24	1		*REAR DOOR TEL NO.STICKER (RH)	Necessary	10.00 FS	*10.00 FS
25	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (RH)	Necessary	80.00 FS	*80.00 FS
26	1		*REAR TYRE (RH)	Not Necessary	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (S\$)	13,679.25	7,567.30
					- List Item Discount on L Items 20.00/20.00% (S\$)	2,674.65	1,495.46
					Total Parts (S\$)	11,004.60	6,071.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,400.00	600.00
2	SPRAY PAINTING CHARGE	New	1,200.00	400.00
3	WIRING CHARGE	New	140.00	0.00
4	TUFF KOTE	New	160.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX UNDERCARRIAGE (RR)	New	400.00	150.00
7	RE-SET REAR ABS SYSTEM	New	400.00	0.00
8	TRANSFER OF DOOR MECHANISM REAR	New	80.00	60.00
9	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
10	FOUR WHEEL ALIGNMENT	New	120.00	60.00
11	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	180.00
Gross Labour Cost (S\$)			4,730.00	1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >