

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG20010617/KVD3Q2

**Date:** 30/12/2020

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001449432

**Claimant**  
**Vehicle No :** EH5757R

**Insured Vehicle No :** YP3784X

Date of Loss: 30/09/2020

Nature of Claim: TP

Claim No: 248182

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **EH5757R**

Make & Model: SUBARU FORESTER, 2.0 X (A)

Engine No: FB20YB47056

Reg. Date: 30/11/2017 (Man. Year: 2017)

Chassis No: JF1SJ5KC5JG100489

Colour: Metallic Pearl White

Odometer: 61170 km

Engine Capacity: 1995 cc

Market Value/New Car

Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/60R17

Rear Tyre Size: 225/60R17

Front Left Side: Yokohama 8 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side: Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,540.00	4,669.32	9,870.68	67.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,980.00	1,720.00	2,260.00	56.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$)</b>	<b>18,520.00</b>	<b>6,389.32</b>	<b>12,130.68</b>	<b>65.50</b>
<b>Approved Total (Overridden) (\$)</b>		<b>5,100.00</b>		
<b>Nett Amount (\$)</b>	<b>18,520.00</b>	<b>5,100.00</b>	<b>13,420.00</b>	<b>72.46</b>

### INSPECTION

Date of Assignment: 02/10/2020

Date Inspected: 05/10/2020 Inspected At:

Meng Whee Bros Motor Service (HQ)  
10 Ang Mo Kio Industrial Park 2A,  
#05-25, AMK Autopoint  
Singapore 568047

Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2020)
<b>Parts:</b>	M1-SUV	SUBARU FORESTER 2.0 X (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for EH5757R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,880.00 F	*1,200.80 FL
2	1		*REAR TAILGATE LOCK	Dented	620.00 F	*264.00 FL
3	1		*REAR TAILGATE EMBLEM 4WD	Necessary	110.00 F	*48.00 FL
4	1		*REAR TAILGATE EMBLEM FORESTER	Necessary	190.00 F	*48.00 FL
5	1		*REAR TAILGATE LOGO	Necessary	280.00 F	*62.00 FL
6	1		*REAR TAILGATE GARNISH	Cracked	580.00 F	*306.00 FL
7	1		*REAR TAILGATE EMBLEM SUBARU	Necessary	190.00 F	*48.00 FL
8	1		*REAR END PANEL	Bent	780.00 F	*425.30 FL
9	1		*REAR END PANEL GARNISH	Serviceable	320.00 F	*- FL
10	1		*REAR WINDSCREEN GLASS	Deep Cut	1,480.00 F	*888.20 FL
11	1		*REAR WINDSCREEN MOULDING	Necessary	280.00 F	*64.20 FL
12	1		*NUMBER PLATE GARNISH	No such part	300.00 F	*- FL
13	1		*REAR BUMPER	Dented/Cracked	960.00 F	*600.30 FL
14	1		*REAR BUMPER REINFORCEMENT	Bent	580.00 F	*320.30 FL
15	1		*REAR BUMPER SIDE RETAINER	Serviceable	300.00 F	*- FL
16	1		*REAR BUMPER LAMP RETAINER	Serviceable	280.00 F	*- FL
17	1		*REAR BUMPER TOW HOOK COVER	Dented	180.00 F	*28.00 FL
18	1		*REAR BUMPER COVER	Distorted	220.00 F	*138.00 FL
19	1		*TAILLAMP	N/s Cut/O/s Serviceable	1,200.00 F	*437.30 FL
20	1		*REAR EXHAUST CHROME	Serviceable	480.00 F	*- FL
21	1		*REAR EXHAUST	Repair	1,250.00 F	*- FL
22	1		*REAR EXHAUST MOUNTING	Serviceable	120.00 F	*- FL
23	1		*REVERSE CAMERA	Serviceable	400.00 F	*- FL
24	1		*REAR NUMBER PLATE	Bent	60.00 FS	*45.00 FS
25	1		*REAR BUMPER CLIPS	Necessary	120.00 FS	*50.00 FS
26	1		*REAR BUMPER TOP GARNISH COVER	Cracked	560.00 FS	*350.00 FS
27	1		*REVERSE SENSOR	Dented	300.00 FS	*200.00 FS
28	1		*SEALANT	Necessary	80.00 FS	*40.00 FS
29	1		*REAR TAILGATE WEATHERSTRIP (\$163.20 (50%))	Cut	440.00 FS	*81.60 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>14,540.00</b>	<b>5,645.00</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	0.00	975.68
<b>Total Parts (\$\$)</b>	<b>14,540.00</b>	<b>4,669.32</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS	New	200.00	120.00
2	TO REMOVE AND INSTALL REAR CARBIN RACK, PLANK, CARPART ETC	New	500.00	60.00
3	TO REMOVE AND INSTALL REAR TAILGATE, HINGES, ABSORBER, BUMPER, REAR END PANEL ETC AND STRAIGHTEN REAR CHASSIS FRAME ETC	New	1,000.00	600.00
4	TO TRANSFER TAILGATE MECHANISM ETC	New	200.00	60.00
5	CHASSIS ALIGNER	New	320.00	0.00
6	TO APPLY PUTTY, PRIMER AND RESPRAY PAINT ON AFFECTED AREA	New	1,200.00	800.00
7	TO APPLY ANTIRUST ON AFFECTED AREA	New	380.00	60.00
8	TO CHECK REAR WIRING SYSTEM	New	180.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,980.00</b>	<b>1,720.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >