

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 277H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	REAR BUMPER CENTER - BLACK	NOT NECESSARY	451.25	-
10	REAR BUMPER CLIPS	NOT NECESSARY	22.00	-
1	REAR BUMPER FOGLAMP	NOT NECESSARY	201.50	-
	LESS 20% DISCOUNT		-226.83	-
			907.32	-
<u>NETT ITEMS</u>				
1	NO PLATE (S) W/TRIM COVER (N)	CUT	55.00	55.00
1	REVERSE SENSOR (N)	NOT NECESSARY	180.00	-
	LESS 10% DISCOUNT		-23.50	-5.50
			211.50	49.50
<u>LABOUR</u>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		350.00	320.00
	SPRAYPAINT CHARGE.		250.00	200.00
	R/I REVERSE SENSOR.		120.00	30.00
			720.00	550.00
GRAND TOTAL			1,838.82	599.50
RECOMMENDED COST OF REPAIRS (CONFIRMED)				599.50

Report Ref No. NS/INC20010620/Eyd3e2



CHEN TSUE YEE

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.