

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD		Ref:	CC4/ASM20010621/Aba3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	22/02/2021	
	ATTN:RICHARD			Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJY 6287A	Veh. Inspected		SKT 7388A	
	Policy No.	GA550221/1	Coverage (\$)		0.00	
	Claim No.	S0M02USG	Excess (\$)		0.00	
	Assign From		Assign Date		02/10/2020	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA SIENTA	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	NCP815218990	Colour		PURPLE	
	Odometer	134704 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/50 R16	GOODYEAR		6 mm	
	L/H Front Tyre	195/50 R16	GOODYEAR		6 mm	
	R/H Rear Tyre	195/50 R16	GOODYEAR		6 mm	
	L/H Rear Tyre	195/50 R16	GOODYEAR		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	01/10/2020	Inspection Dat	е	05/10/2020	
	Survey held at	MG SOLUTION PTE LTD	-			
		23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	STIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				
5b.	ESTIMATED NORM	· · ·				