

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III20010631/QTD3E2

Date: 16/11/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No : SKT7561R	Insured Vehicle No :	SHA1853Z
Date of Loss: 02/10/2020	Nature of Claim:	TP Claim No: MCT20100018

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT7561R	Engine No:	27492030379491
Make & Model:	MERCEDES-BENZ E250, 1.8 (A)	Chassis No:	WDD2120362B152833
Reg. Date:	23/06/2015 (Man. Year: 2015)	Odometer:	118810 km
Colour:	Blue		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40Z R18	Rear Tyre Size:	245/40Z R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,142.42	9,104.88	9,037.54	49.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,770.00	2,180.00	2,590.00	54.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,912.42	11,284.88	11,627.54	50.75
Approved Total (Overridden) (S\$)		9,000.00		
(S\$)	22,912.42	9,000.00	13,912.42	60.72
+ GST 7.00/7.00% (S\$)	1,603.87	630.00	973.87	60.72
Nett Amount (S\$)	24,516.29	9,630.00	14,886.29	60.72

INSPECTION

Date of Assignment:	05/10/2020	
Date Inspected:	06/10/2020 Inspected At:	Tech Choon Automotive Pte Ltd (HQ) 60 Jalan Lam Huat, #05-45 Carros Centre Singapore 737869
Estimated Period of Repair:	6.0 days	

Adjuster: OI SUN PIN**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Nov 2020)
Parts:	143	MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT7561R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL FRONT LH	Repair	2,195.60 FL	*- FL
2	1		*DOOR MOULDING FRONT LH	Serviceable	129.00 FL	*- FL
3	1		*DOOR CHROME MOULDING LOWER F/LH	Serviceable	130.00 FL	*- FL
4	1		*DOOR OPER HANDER OUTER FRONT LH	Serviceable	416.00 FL	*- FL
5	1		*DOOR RUBBER FRONT LH	Serviceable	305.25 FL	*- FL
6	1		*FENDER FRONT LH	Dented	832.50 FL	*832.50 FL
7	1		*FENDER CHROME MOULDING LOWER F/LH	Necessary	40.70 FL	*40.70 FL
8	12		*FENDER DUST COVER CLIP	Necessary	96.00 FL	*30.00 FL
9	1		*FENDER DUST COVER LH (FRONT PART)	Crumpled	195.00 FL	*195.00 FL
10	1		*FENDER DUST COVER LH (REAR PART)	Crumpled	205.00 FL	*185.00 FL
11	1		*WINDSCREEN WASHER TANK	Serviceable	185.00 FL	*- FL
12	1		*WINDSCREEN WASHER MOTOR SEAL RING	Serviceable	8.00 FL	*- FL
13	1		*WINDSCREEN WASHER TANK MOTOR	Serviceable	96.20 FL	*- FL
14	1		*BUMPER FRONT #10	Crumpled	1,304.25 FL	*1,304.25 FL
15	1		*BUMPER BRACKET LH #40	Necessary	20.00 FL	*20.00 FL
16	1		*BUMPER BRACKET LH #70	Necessary	85.10 FL	*85.10 FL
17	1		*BUMPER BRACKET CENTRE #80	Serviceable	160.00 FL	*- FL
18	1		*SIDE MIRROR HOUSING LH #10	Serviceable	962.00 FL	*- FL
19	1		*SIDE MIRROR COVER WITH SIGNAL LIGHT #100	Scratched	360.75 FL	*360.75 FL
20	1		*SIDE MIRROR BTM COVER #80	Scratched	115.00 FL	*115.00 FL
21	1		*SIDE MIRROR GLASS #40	Serviceable	240.50 FL	*- FL
22	1		*FENDER BRACKET LH #100	Necessary	12.00 FL	*12.00 FL
23	2		*BUMPER SENSOR FRONT LH	Shorted	350.00 FL	*280.00 FL
24	1		*HEADLAMP UNIT LH #10	Crumpled	4,532.50 FL	*3,927.00 FL
25	1		*HEADLAMP VOLTAGE CONVERTER #130	Serviceable	851.00 FL	*- FL
26	1		*HEADLAMP LIGHT RANGE @180	Serviceable	638.25 FL	*- FL
27	2		*FENDER LH RIVET #90	Necessary	12.00 FL	*12.00 FL
28	1		*HEADLAMP PANEL LH	Cracked	268.00 FL	*268.00 FL
29	1		*BUMPER BRACKET HEADLAMP LOWER	Serviceable	85.10 FL	*- FL
30	1		*HEADLAMP BRACKER LOWER	Deformed	268.00 FL	*268.00 FL
31	1		*FOG LIGHT CHROM #225	Serviceable	114.70 FL	*- FL
32	1		*FOG LIGHT COVER #227	Serviceable	31.45 FL	*- FL
33	1		*FOG LIGHT HOUSING #215	Serviceable	51.80 FL	*- FL
34	1		*GRILLE LIST PRICE CHROM CENTRE #120	Cracked	333.00 FL	*333.00 FL
35	1		*GRILLE COVER #40	Serviceable	185.00 FL	*- FL
36	4		*GRILL COVER CHROM #80	Serviceable	180.00 FL	*- FL
37	1		*GRILLE STAR LOGO #70	Serviceable	130.00 FL	*- FL
38	1		*GRILLE STAR BEAN #50	Serviceable	65.00 FL	*- FL
39	1		*GRILLE BASE #20	Serviceable	205.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*GRILLE CARRIER #240	Serviceable	250.00 FL	*- FL
41	1		*SPORT RIM FRONT LH WHEEL	Scratched	1,650.00 FS	*1,250.00 FS
42	1		*TYRE (MICHELIN PILOT SPORT) 245/40 ZR18	Serviceable	680.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,974.65	9,518.30
- List Item Discount on L Items 5.00/5.00% (\$)	832.23	413.42

Total Parts (\$)	18,142.42	9,104.88
-------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX FRONT LH DOOR MECHANISM	New	285.00	0.00
2	TO USE COMPUTER FOR DIAGNOSTIC & CLEAR FAULT CODES FULL VEHICLE SYSTEM	New	385.00	250.00
3	TO REPLACE FRONT LH DOOR PANEL, FENDER, FRONT BUMPER KIT & AFFECTED PORTION & ADJUSTMENT	New	1,450.00	900.00
4	TO REPLACE LH HEADLAMP ASSY, ADJUSTMENT & CHECK WIRING	New	150.00	30.00
5	TO USE COMPUTER CODING HEADLAMP CONTROL UNIT	New	450.00	0.00
6	TO SPRAY PAINTING FOR AFFECTED PORTION	New	1,500.00	900.00
7	TO SPRAY UNDERCOAT	New	185.00	40.00
8	TO TEST & ADJUST FOUR WHEEL COMPUTER ALIGNMENT	New	280.00	60.00
9	TO REPLACE SIDE MIRROR & INSTALL	New	85.00	0.00
Gross Labour Cost (S\$)			4,770.00	2,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >