

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20010642/DYF3Q2

Date: 10/11/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00034322001
Claimant Vehicle No :	SLW5464Z	Insured Vehicle No :	YP3080T
Date of Loss:	01/10/2020	Nature of Claim:	TP
		Claim No:	SNM20D203655/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW5464Z	Engine No:	4GR0393451
Make & Model:	LEXUS IS, 250 (A)	Chassis No:	JTHBK262905056298
Reg. Date:	12/03/2008 (Man. Year: 2007)	Odometer:	157772 km
Colour:	Blue		
Engine Capacity:	2500 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/35R19	Rear Tyre Size:	235/35R19
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,656.46	8,061.36	12,595.10	60.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,920.00	1,620.00	2,300.00	58.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,576.46	9,681.36	14,895.10	60.61
Approved Total (Overridden) (S\$)		7,500.00		
(S\$)	24,576.46	7,500.00	17,076.46	69.48
+ GST 7.00/7.00% (S\$)	1,720.35	525.00	1,195.35	69.48
Nett Amount (S\$)	26,296.81	8,025.00	18,271.81	69.48

INSPECTION

Date of Assignment: 02/10/2020

Date Inspected: 05/10/2020 Inspected At:

JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Nov 2020)
Parts:	143	LEXUS IS 250 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW5464Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP LH/RH	O/s Cracked/N/s Not Necessary	4,776.50 FL	*2,388.25 FL
2	1		*HEAD LAMP LOWER BRACKET RH	Not Necessary	380.25 FL	*- FL
3	1		*HEAD LAMP ECU RH	Not Necessary	988.76 FL	*- FL
4	1		*HEAD LAMP WIRE HARNESS RH	Torn	888.82 FL	*888.82 FL
5	1		*FRONT FENDER RH	Repair	1,163.70 FL	*- FL
6	1		*FRONT FENDER INNER SHIELD RH	Torn	479.40 FL	*185.60 FL
7	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	25.00 FL	*25.00 FL
8	1		*FRONT BUMPER UNDER COVER	Torn	723.55 FL	*285.67 FL
9	1		*FRONT BUMPER FOG LAMP WIRE HARNESS RH	Not Necessary	534.87 FL	*- FL
10	1		*FRONT REINFORCEMENT BAR	Not Necessary	783.00 FL	*- FL
11	1		*FRONT GRILLE LOGO	Dislodged	179.09 FL	*92.51 FL
12	1		*SET FRONT BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
13	2		*FRONT BUMPER SENSOR HOLDER	Not Necessary	65.60 FL	*- FL
14	1		*FRONT BUMPER SENSOR WIRE HARNESS	Broken	400.85 FL	*400.85 FL
15	2		*FRONT BUMPER SENSOR WIRE HARNESS	Damaged	874.51 FS	*220.00 FS
16	1		*FRONT BUMPER }	Broken	2,800.00 FS	*2,800.00 FS
17	1		*FRONT GRILLE }	Broken	1,200.00 FS	*- FS
18	1		*FRONT LOWER GRILLE }	Not Necessary	1,200.00 FS	*- FS
19	1		*FRONT SIDE GRILLE LH/RH }	O/s Broken/N/s Not Necessary	500.00 FS	*- FS
20	1		*FRONT BUMPER FOG LAMP R/H	Broken	2,000.00 FS	*800.00 FS
21	1		*FRONT BUMPER LOWER LID	Cut	1,800.00 FS	*800.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,798.90	8,921.70
- List Item Discount on L Items 10.00/20.00% (\$\$)	1,142.44	860.34
Total Parts (\$\$)	20,656.46	8,061.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	1,600.00	700.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	1,400.00	700.00
3	TO TUFF COAT DAMAGED AREAS	New	300.00	0.00
4	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
5	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	150.00
6	TO RNR FRONT BUMPER SENSOR TO ASSIST WORK LOAD	New	120.00	40.00
Gross Labour Cost (S\$)			3,920.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >