

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20010643/R1RA3Q2

Date: 15/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SDK8531B **Insured Vehicle No :** SLP7862G

Date of Loss: 28/09/2020 **Nature of Claim:** TP **Claim No:** 9727249954SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDK8531B		
Make & Model:	VOLKSWAGEN BEETLE CABRIOLET, 1.2 TSI DSG (A)	Engine No:	CYV588384
Reg. Date:	13/02/2018 (Man. Year: 2017)	Chassis No:	WVWZZZ16ZJM504805
Colour:	Blue	Odometer:	37949 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45Z R18	Rear Tyre Size:	235/45Z R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,569.07	1,521.54	1,047.53	40.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,760.00	7,440.00	2,320.00	23.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,329.07	8,961.54	3,367.53	27.31
+ GST 7.00/7.00% (S\$)	863.03	627.31	235.72	27.31
Nett Amount (S\$)	13,192.10	9,588.85	3,603.25	27.31
+ Car Rental (9.0 x S\$80.00/day + 7.00% GST) (S\$)		770.40		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		10,361.25		

INSPECTION

Date of Assignment: 07/10/2020

Date Inspected: 07/10/2020 Inspected At: Volkswagen Group Singapore Pte Ltd
247 Alexandra Road
Singapore 159934

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HOLDER FOR COVER BUMPER FRT BUMPER UPPER BRACKET LH	Serviceable	43.54 FS	*- FS
2	1		*HOLDER FOR COVER BUMPER FRT BUMPER UPPER BRACKET RH	Serviceable	43.54 FS	*- FS
3	1		*GUIDE PIECE BUMPER SIDE BRACKET RH	Serviceable	34.31 FS	*- FS
4	1		*FENDER RHF FENDER	Bent	615.49 FS	*615.49 FS
5	1		*WHEELHOUSE LINER FENDER LINER RH	Serviceable	166.47 FS	*- FS
6	6		*EXPANDING NUT	Serviceable	11.82 FS	*- FS
7	1		*FENDER RHR FENDER	Bent	869.81 FS	*869.81 FS
8	1		*PROTECTIVE FOIL RHR FENDER FOIL	Necessary	36.24 FS	*36.24 FS
9	1		*COVER FOR DOOR PRIMED RHS DOOR LOWER MLDG	Serviceable	582.37 FS	*- FS
10	1		*DECORATIVE MOULDING RH DOOR LOWER MLDG CHROM	Serviceable	165.48 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **2,569.07** **1,521.54**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK H/LAMP ALIGNMENT & WIRING	New	280.00	0.00
3	LABOUR	New	4,200.00	3,360.00
4	SPRAY PAINTING	New	4,800.00	3,600.00
Gross Labour Cost (\$\$)			9,760.00	7,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >