

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Oct 2020		06 Oct 2020 11:06 Edit Adj Rpt	S\$7,500.00 Edit Estimates	S\$7,500.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	KOH YILING EILEEN , ID: S8210940D, Tel: +6597318515		
Main Claimant:	EXCEL LIMOUSINE SERVICES , Co. Reg. No.: 53258814B		
Vehicle Reg. No.:	SKN5000M	Date of Loss:	02/10/2020 08:00 - :59 [45 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 248271	Policy/Cover Note No.:	1000847862 (Comprehensive) Coverage: 15/11/2018 - 14/11/2020
Vehicle Reg. No. (Insured):	SLT8596Y	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 07/10/2020]		
Driver/Custodian (Insured):	KOH YILING EILEEN (38 / Female) , NRIC: S8210940D, Tel: +6597318515 Email:		
Adj Asg. Remarks:	Liab: clear. Direct survey by LKK.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SKN5000M (248271)**
[SLT8596Y]
TP
EXCEL LIMOUSINE SERVICES
Oct 2 2020 8:00AM
[KOH YILING EILEEN]
Fastech Auto Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#) ▼

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/10/20 17:17	Odometer Reading	Load JPG	☒
2	07/10/20 17:17	Chassis Number	Load JPG	☒
3	07/10/20 17:18	General View	Load JPG	☒
4	07/10/20 17:18	General View	Load JPG	☒
5	07/10/20 17:18	General View	Load JPG	☒
6	07/10/20 17:18	General View	Load JPG	☒
7	07/10/20 17:18	General View	Load JPG	☒
8	07/10/20 17:18	General View	Load JPG	☒
9	07/10/20 17:18	General View	Load JPG	☒
10	07/10/20 17:18	General View	Load JPG	☒
11	07/10/20 17:18	General View	Load JPG	☒
12	07/10/20 17:18	General View	Load JPG	☒
13	07/10/20 17:18	General View	Load JPG	☒
14	07/10/20 17:18	General View	Load JPG	☒
15	07/10/20 17:18	General View	Load JPG	☒
16	07/10/20 17:18	General View	Load JPG	☒
17	07/10/20 17:18	General View	Load JPG	☒
18	07/10/20 17:18	General View	Load JPG	☒
19	07/10/20 17:18	General View	Load JPG	☒
20	07/10/20 17:18	General View	Load JPG	☒
21	07/10/20 17:18	General View	Load JPG	☒
22	07/10/20 17:18	General View	Load JPG	☒
23	07/10/20 17:18	General View	Load JPG	☒
24	07/10/20 17:18	General View	Load JPG	☒
25	07/10/20 17:18	General View	Load JPG	☒
26	07/10/20 17:18	General View	Load JPG	☒
27	07/10/20 17:18	General View	Load JPG	☒
28	07/10/20 17:18	General View	Load JPG	☒
29	07/10/20 17:18	General View	Load JPG	☒
30	07/10/20 17:18	General View	Load JPG	☒
31	07/10/20 17:18	General View	Load JPG	☒
32	07/10/20 17:18	General View	Load JPG	☒
33	07/10/20 17:18	General View	Load JPG	☒
34	07/10/20 17:18	General View	Load JPG	☒
35	07/10/20 17:18	General View	Load JPG	☒

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	07/10/20 17:18	General View	 Load JPG	☒
37	07/10/20 17:18	General View	 Load JPG	☒
38	07/10/20 17:18	General View	 Load JPG	☒
39	07/10/20 17:18	General View	 Load JPG	☒
40	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
41	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
42	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
43	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
44	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
45	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
46	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
47	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
48	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
49	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
50	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
51	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
52	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
53	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
54	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
55	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
56	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
57	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
58	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
59	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
60	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
61	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
62	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
63	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
64	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
65	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
66	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
67	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
68	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
69	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
70	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
71	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
72	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
73	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
74	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
75	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
76	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
77	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
78	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
79	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
80	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
81	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
82	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
83	07/10/20 17:21	Reinspection Photo	Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
85	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
86	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
87	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
88	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
89	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
90	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
91	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
92	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
93	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
94	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
95	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
96	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
97	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
98	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
99	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
100	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
101	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
102	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
103	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
104	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
105	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
106	07/10/20 17:21	Reinspection Photo	 Load JPG	☒
107	13/10/20 09:32	Photo After Spray	 Load JPG	☒
108	13/10/20 09:32	Photo After Spray	 Load JPG	☒
109	13/10/20 09:32	Photo After Spray	 Load JPG	☒
110	13/10/20 09:32	Photo After Spray	 Load JPG	☒
111	13/10/20 09:32	Photo After Spray	 Load JPG	☒
112	13/10/20 09:32	Photo After Spray	 Load JPG	☒
113	13/10/20 09:32	Photo After Spray	 Load JPG	☒
114	13/10/20 09:32	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/10/20 10:57	Accident Statement From:OD - Reg. No: SLT8596Y, Claimant: Koh YiLing Eileen	 Load PDF	
2	05/10/20 10:57	TPD SKN5000M GIA REPORT From:OD - Reg. No: SLT8596Y, Claimant: Koh YiLing Eileen	 Load PDF	
3	05/10/20 10:57	OI SLT8596Y - POLICY SCHEDULE From:OD - Reg. No: SLT8596Y, Claimant: Koh YiLing Eileen	 Load PDF	
4	06/10/20 11:02	PRI Email	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/MSG20010645/UTF3S2**Date:** 19/10/2020REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1000847862
Claimant Vehicle No :	SKN5000M	Insured Vehicle No :	SLT8596Y
Date of Loss:	02/10/2020	Nature of Claim:	TP
		Claim No:	248271

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN5000M	Engine No:	L15B4404106
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11204105
Reg. Date:	23/12/2016 (Man. Year: 2016)	Odometer:	213561 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,801.70	6,823.52	10,978.18	61.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,780.00	2,610.00	2,170.00	45.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	22,581.70	9,433.52	13,148.18	58.22
Approved Total (Overridden) (\$\$)		7,500.00		
(\$\$)	22,581.70	7,500.00	15,081.70	66.79
+ GST 7.00/7.00% (\$\$)	1,580.72	525.00	1,055.72	66.79
Nett Amount (\$\$)	24,162.42	8,025.00	16,137.42	66.79

INSPECTION

Date of Assignment:	06/10/2020		
Date Inspected:	05/10/2020	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	7.0 days		

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

10/19/2020

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Oct 2020)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKN5000M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	88.20 F	*88.20 FL
2	1		*REAR WINDSCREEN	Not Necessary	1,650.00 F	*- FL
3	1		*TAILGATE	Badly Dented	1,100.90 F	*953.00 FL
4	1		*TAILGATE OUTER GARNISH	Cracked	315.20 F	*315.20 FL
5	1		*TAILGATE H LOGO	Necessary	32.50 F	*32.50 FL
6	1		*TAILGATE VEZEL EMBLEM	Necessary	56.50 F	*56.50 FL
7	1		*TAILGATE REFLECTORS	O/s Scratched	729.20 F	*280.40 FL
8	1		*TAILGATE INNER LOCK	Twisted	181.90 F	*181.90 FL
9	1		*TAILGATE LOCK STRIKER	Not Necessary	48.60 F	*- FL
10	1		*TAILGATE INNER TRIM BOARD	Deformed / Cracked	368.20 F	*368.20 FL
11	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
12	1		*TAILGATE INNER HANDLE HOLDER	Not Necessary	32.00 F	*- FL
13	2		*TAILGATE DAMPERS	Not Necessary	385.00 F	*- FL
14	1		*TAILGATE WEATHERSTRIP	Twisted	199.00 F	*199.00 FL
15	1		*REAR BUMPER	Dented	863.50 F	*549.20 FL
16	2		*REAR BUMPER SIDES	Repair	790.20 F	*- FL
17	2		*REAR BUMPER REFLECTORS	Not Necessary	330.00 F	*- FL
18	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
19	1		*REAR BUMPER LOWER UNDER COVER	Twisted	312.00 F	*312.00 FL
20	1		*SET REAR BUMPER LOWER UNDER COVER CLIPS	Necessary	50.00 F	*50.00 FL
21	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	90.00 F	*- FL
22	1		*REAR END PANEL	Badly Dented	517.00 F	*517.00 FL
23	1		*REAR END PANEL TOP GARNISH	Twisted	188.00 F	*188.00 FL
24	2		*TAILLAMPS	Scratched / Cracked	970.00 F	*921.00 FL
25	2		*TAILLAMP HOUSING PANELS	Repair	700.00 F	*- FL
26	1		*REAR FLOOR PANEL	Crumpled / Buckled	1,330.20 F	*912.30 FL
27	1		*REAR FLOOR PANEL TOP BOARD	Torn	326.50 F	*326.50 FL
28	1		*REAR FLOOR PANEL TOOLS SPONGE	Torn	688.00 F	*522.30 FL
29	1		*REAR LOCK SENSOR	Cracked	295.00 F	*295.00 FL
30	2		*REAR FENDERS	Repair	1,982.00 F	*- FL
31	1		*REAR FENDER INNER TRIMS	O/s Deformed	900.00 F	*388.20 FL
32	1		*REAR EXHAUST	Repair	785.20 F	*- FL
33	1		*REAR EXHAUST HEATSHIELD	Not Necessary	188.90 F	*- FL
34	2		*REAR FENDER OUTER PROTECTORS	Torn	598.00 F	*598.00 FL
35	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
36	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
37	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
38	1		*SET REAR FLOOR PANEL INSULATOR	Not fitted	180.00 FS	*- FS
39	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **17,801.70** **8,454.40**
- List Item Discount on L Items 0.00/20.00% (\$\$) 0.00 1,630.88

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	17,801.70
						6,823.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING.	New	50.00	30.00
2	TO DISMANTLE & REFIX REAR WINDSCREEN.	New	150.00	120.00
3	TO TRANSFER TAILGATE MECHANISM.	New	100.00	60.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.	New	150.00	80.00
5	TO DISMANTLE & REFIX REAR EXHAUST.	New	100.00	60.00
6	TO DISMANTLE & REFIX FUEL TANK.	New	100.00	60.00
7	TO SPRAY RUST PROOFING.	New	150.00	100.00
8	TO MOUNT VEHICLE ON CAR O-LINER.	New	380.00	0.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS.	New	1,800.00	1,300.00
10	TO PUTTY & SPRAY PAINTING.	New	1,800.00	800.00
Gross Labour Cost (\$\$)			4,780.00	2,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >