

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBB 111D**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	DEFORMED	851.32	569.00
1	FRONT BUMPER RETAINER LH	NECESSARY	113.75	42.00
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	636.65	-
1	FRONT FENDER LINER LH	NOT NECESSARY	201.35	-
1	FRONT FENDER LINER PAD LH	NOT NECESSARY	70.28	-
1	HEAD LAMP LH	CRACKED	1,274.65	1,274.65
1	FOG LAMP COVER LH	NOT NECESSARY	120.95	-
1	AIR INTAKE DUCT	NOT NECESSARY	156.20	-
	LESS 25% DISCOUNT		-856.29	-471.41
			2,568.86	1,414.24
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	SET FRONT FENDER LINER CLIP (SN)	NOT NECESSARY	50.00	-
			100.00	30.00
	<b><u>LABOUR</u></b>			
	TO REMOVE AND REPAIR ABOVE PART.INCLUSIVE OF THE REPAIR OF FRONT FENDER LH.		700.00	400.00
	TO SPRAY PAINTING ON AFFECTED AREA.		800.00	400.00
			1,500.00	800.00
	<b>GRAND TOTAL</b>		<b>4,168.86</b>	<b>2,244.24</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,800.00</b>

Report Ref No. CS/FCI20010646/Atd3e2

**ADRIAN LING WAI PING****B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI****Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.