

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20010647/UGA3Q2
Date: 10/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1800030202	
Claimant Vehicle No : SKH1549E	Insured Vehicle No : SLX409L	
Date of Loss: 05/10/2020	Nature of Claim: TP	Claim No: 4357586845SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKH1549E		
Make & Model: VOLVO XC60, 2.0 T5 (A)	Engine No: B4204T71095793	
Reg. Date: 08/11/2012 (Man. Year: 2012)	Chassis No: YV1DZ475BD2366911	
Colour: Blue	Odometer: 139757 km	
Engine Capacity: 1999 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60R18	Rear Tyre Size: 235/60R18	
Front Left Side: Maxxis 6 mm	Rear Left Side: Maxxis 6 mm	
Front Right Side: Maxxis 6 mm	Rear Right Side: Maxxis 6 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,115.70	9,088.71	15,026.99	62.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,810.00	1,280.00	1,530.00	54.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,925.70	10,368.71	16,556.99	61.49
Approved Total (Overridden) (S\$)		7,300.00		
(S\$)	26,925.70	7,300.00	19,625.70	72.89
+ GST 7.00/7.00% (S\$)	1,884.80	511.00	1,373.80	72.89
Nett Amount (S\$)	28,810.50	7,811.00	20,999.50	72.89
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		50.00		
Nett Liability (S\$)		8,183.00		
Global Sum Settlement (S\$)		8,150.00		

INSPECTION

Date of Assignment: 05/10/2020		
Date Inspected: 05/10/2020	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883

3/10/2021

Adjuster Report

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	3,200.65 F	*1,845.32 FL
2	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	1,545.15 F	*- FL
3	1		*FRONT BUMPER SIDE HOLDER N/S	Cracked	150.00 F	*100.50 FL
4	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
5	1		*FRONT BUMPER LOWER	Cut	1,488.15 F	*822.35 FL
6	1		*HEADLAMP N/S	Cracked	3,300.00 F	*1,650.00 FL
7	1		*FRONT FENDER N/S	Badly Dented	2,488.15 F	*1,020.00 FL
8	1		*FRONT FENDER INNER SHIELD N/S	Distorted	466.50 F	*288.00 FL
9	1		*SET FRONT FENDER INNER SHIELD CLIPS N/S	Necessary	50.00 F	*50.00 FL
10	1		*FRONT DOOR N/S	Repair	3,255.15 F	*- FL
11	1		*FRONT SHOCK ABSORBER N/S	Serviceable	988.15 F	*- FL
12	1		*FRONT KNUCKLE ARM N/S	Bent	1,255.50 F	*980.00 FL
13	1		*FRONT KNUCKLE ARM BEARING N/S	Necessary	650.00 F	*455.00 FL
14	1		*FRONT LOWER ARM N/S	Bent	1,099.15 F	*699.00 FL
15	1		*FRONT STEERING TIE ROD N/S	Twisted	399.00 F	*399.00 FL
16	1		*FRONT DRIVE SHAFT N/S	Serviceable	1,880.15 F	*- FL
17	1		*FRONT SPORT RIM N/S	Cut	1,600.00 F	*1,050.00 FL
18	1		*FRONT TYRE N/S (60%)	Punctured	250.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,115.70	9,559.17
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	470.46
Total Parts (\$\$)	24,115.70	9,088.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIIRNG	New	80.00	20.00
2	TO SPRAY RUST PROOFING	New	80.00	30.00
3	TO CONDUCT WHEEL ALIGNMENT	New	120.00	80.00
4	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	New	380.00	150.00
5	TO REFILL AIR CON GAS	New	150.00	0.00
6	LABOUR FOR PANEL BEATING & RPELACE PARTS	New	800.00	400.00
7	TO PUTTY & SPRAY PAINTING	New	1,200.00	600.00
Gross Labour Cost (S\$)			2,810.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >