

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20010661/R1GS3Q2

**Date:** 17/02/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900081411

**Claimant**  
**Vehicle No :** SLM9616D **Insured Vehicle No :** SMK614S

Date of Loss: 01/10/2020 Nature of Claim: TP Claim No: 5282581511SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLM9616D</b>		
Make & Model:	KIA NIRO, 1.6 HYBRID GDI DCT SUNROOF (A)	Engine No:	G4LEHS183208
Reg. Date:	19/04/2017 (Man. Year: 2017)	Chassis No:	KNACC81CVH5061293
Colour:	Blue	Odometer:	62360 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,990.80	1,085.60	905.20	45.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,060.00	2,060.00	1,000.00	32.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>5,050.80</b>	<b>3,145.60</b>	<b>1,905.20</b>	<b>37.72</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	353.56	220.19	133.37	37.72
<b>Nett Amount (\$\$)</b>	<b>5,404.36</b>	<b>3,365.79</b>	<b>2,038.57</b>	<b>37.72</b>
<b>+ Car Rental (7.0 x S\$100.00/day + 7.00% GST) (\$\$)</b>		749.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>4,116.79</b>		

### INSPECTION

Date of Assignment: 05/10/2020

Date Inspected: 06/10/2020 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339

Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD RASUL

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*BRACKET ASSY --RR BUMPER SIDE ,LH	Cut	20.00 FS	*20.00 FS
3	1		*BRACKET ASSY --RR BUMPER SIDE ,RH	Not Necessary	20.00 FS	*- FS
4	1		*STAY -RR BUMPER LH	Serviceable	53.60 FS	*- FS
5	1		*STAY -RR BUMPER RH	Not Necessary	53.60 FS	*- FS
6	1		*BRACKET -RR BEAM UPR MTG ,LH	Serviceable	4.80 FS	*- FS
7	1		*BRACKET -RR BEAM UPR MTG ,RH	Serviceable	4.80 FS	*- FS
8	1		*BEAM -RR BUMPER	Serviceable	208.80 FS	*- FS
9	1		*BRACKET -RR RAIL LWR MTG	Not Necessary	4.80 FS	*- FS
10	1		*BRACKET -RR RAIL LWR CTR	Not Necessary	4.80 FS	*- FS
11	1		*BRACKET -SMART KEY MTG	Not Necessary	4.00 FS	*- FS
12	1		*WIRING HARNESS -RR BUMPER	Not Necessary	288.80 FS	*- FS
13	1		*REFLECTOR /REFLEX ASSY -RR LH	Cracked	83.20 FS	*83.20 FS
14	1		*COVER-RR BUMPER ,UPR	Deformed	388.80 FS	*388.80 FS
15	1		*COVER-RR BUMPER ,LWR	Scratched	313.60 FS	*313.60 FS
16	1		*SKID PLATE -RR BUMPER	Serviceable	97.60 FS	*- FS
17	1		*COVER-RR BUMPER SIDE UNDER,LH	Serviceable	21.60 FS	*- FS
18	1		*PIECE -RR BUMPER SIDE ,LH	Cracked	12.80 FS	*12.80 FS
19	1		*MOULDING ASSY -RR BUMPER SIDE ,L	Cut	16.00 FS	*16.00 FS
20	1		*SENSOR ASSY -PARKING ASSIST SYS	Scratched	108.00 FS	*108.00 FS
21	1		*SENSOR ASSY -PARKING ASSIST SYS	Serviceable	108.00 FS	*- FS
22	10		*CLIP	Necessary	8.00 FS	*8.00 FS
23	1		*GARNISH ASSY -QTR SIDE LH	Cut	115.20 FS	*115.20 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**      **1,990.80**      **1,085.60**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	REPAIR REAR END PANEL	New	200.00	200.00
2	RESPRAY REAR END PANEL	New	350.00	350.00
3	RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE ,REPAIR REAR END PANEL	New	1,200.00	600.00
4	REMOVE AND INSTALL PARKING ASSIST	New	60.00	60.00
5	PAINT WORK SPRAY REAR END PANEL,REAR BUMPER AND AFFECTED PORTION	New	1,050.00	700.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
8	SUPPLY REAR NUMBER PLATE WITH FRAME	New	50.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,060.00</b>	<b>2,060.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >