

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

ESTIMATE

GST Reg No : MR-8500111-X

| Reg No : 199405410K | ESTIMATE | GST Reg No : MR-8500111-X |
|---|-----------------|--------------------------------------|
| Invoice Name & Address | | Owner Name & Vehicle Info |
| | Cust No/Name | /LEOW KOK SIONG |
| AIG Asia Pacific Insurance Pte. Ltd. | Reg No/Reg Date | SLM9616D / 19/04/201 |
| MOTOR CLAIM DEPARTMENT | Date In/Mileage | / 0 |
| 78 SHENTON WAY #08-16 | Chassis No | KNACC81CVH5061293 |
| AIG BUILDING | Engine No | G4LEHS183208 |
| SINGAPORE 079120 Contact No 64191000 | Make/Mode1 | KIA/NIRO 1.6 A |
| | Colour/Trim | C3U DEEP CERULEAN B/ WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | | WIP No | | | |
|------------------------------|------------|------------------------|-------------|-----------------|--|-------------------|--|-----|----------------|
| LAX00000 | Credit | 02/10/2020/ 14:51 | QUD | 247 / DonBong | | 22076 | | | |
| | | Description of Good | s / Service | S | Qty | Unit Price | Disc% | | nount |
| E PNT88000 | - | | | | | | | low | 1200.00 |
| | | AMAGED PARTS ON REAR | BUMPER FA | ACE, | | | | | |
| REPAIR RE | EAR END F | PANEL | | | | | | | 60.00 |
| E PNT88000 | ND THETAL | I DADVING ACCICT | | | | | | | 00.00 |
| F DNTOOOOO | | ∟L PARKING ASSIST * | | R | | | | 750 | 1050.00 |
| PAINT WOF | RK SPRAY | REAR END PANEL, REAL | RIMPER | LH PRIP PONCO | | | | • | 7 |
| AND AFFEC | CTED PORT | TION | C DOTTI ETC | -11 KENK HOLDER | . Orke | | | | |
| A 10028901 | | | | | ' | | | | 120.00 |
| TO CARRY | OUT DIAG | GNOSTIC CHECK USING I | HI-SCAN PE | RO TEST | | | | | / |
| USING HI- | | , , | _ П | | П | | | | |
| A 54900099 | | CHASSIS ELECTRICAL | 0.57 | | 57 | ١ | | l | 30.00 |
| CHECK WIR | RING AND | CHASSIS ELECTRICAL | X24EW | | | <u>.</u> | | | 50.00 |
| | | R PLATE WITH FRAME | 96 | | | , | | | 50.00 |
| M SUNDRY | AK NUMBE | IN PLATE WITH FRAME | | | | | | 20 | 50/00 |
| SUNDRIES | | 2 | | | | | | | 50.00 |
| | SSY-RR B | BUMPER SIDE, LH . | | | 1.00 | 25.00 | 20.00 | | 20.00 |
| | | BUMPER SIDE,RH ✓ | | | 1.00 | 25.00 | 20.00 | | 20.00 |
| M STAY-RR B | | | | | 1.00 | 67.00 | 20.00 | | 53.60 |
| M STAY-RR B | UMPER RH | 1× 7 | | | 1.00 | 67.00 | 20.00 | | 53.60 |
| 1 BRACKET-R | R BEAM U | PR MTG,LH - | | | 1.00 | | 20.00 | | 4.80 |
| | | PR MTG,RH ≭ | | | 1.00 | | 20.00 | | 4.80 |
| M BEAM-RR BI M BRACKET-RI | | UD MTC 7 | | | 1.00 | 261.00 | | | 208.80 |
| BRACKET-RI | | | | | 1.00 | | 20.00 | | 4.80 |
| BRACKET-SI | MART KFY | MTG 7 | | | 1.00 1.00 | | 20.00 | 1 | 4.80 |
| WIRING HA | RNESS-RR | BUMPER - | | | 1.00 | 361.00 | | | 4.00 288.80 |
| REFLECTOR, | REFLEX A | ASSY-RR LH CA | | | 1.00 | 104.00 | | | 83.20 |
| 1 COVER-RR E | BUMPER, UI | PR de/ | | | 1.00 | 486.00 | | | 388.80 |
| COVER-RR | BUMPER LI | WR Sept | | | 1.00 | 392.00 | | | 313.60 |
| SKID PLATE | | | | | 1.00 | 122.00 | Constitution of the Consti | | 97.60 |
| COVER-RR | BUMPER S | IDE UNDER, LH | | | 1.00 | 27.00 | 20.00 | | 21.60 |
| Confirm & acc | | | | | ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, | | | | |

Confirm & accepted by

THE THE TOUR KESTEVATION I MY

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen. the rubber seal or other repair requiring the removal of the windscreen.



. 100/05/10K

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info | | | |
|---|---------------------------|--------------------------------------|--|--|
| | Cust No/Name | /LEOW KOK SIONG | | |
| AIG Asia Pacific Insurance Pte. | Reg No/Reg Date | SLM9616D / 19/04/201 | | |
| Ltd. MOTOR CLAIM DEPARTMENT | Date In/Mileage | | | |
| 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 | Chassis No | KNACC81CVH5061293 | | |
| | Engine No | G4LEHS183208 | | |
| | Make/Mode1 | KIA/NIRO 1.6 A | | |
| | Colour/Trim | C3U DEEP CERULEAN B/ WK SATURN BLACK | | |

| Account No | Terms | Date/Time Print | ted | CSE | Operator | | WIP No | | |
|-------------|--------------------------------|--|------------|--------------------|---------------|-----------------|------------|-------|------------------|
| LAX00000 | Credit | 02/10/2020/ 1 | | QUD | 247 / DonBong | | 22076 | | |
| LANUUUU | Creare | Description of | | | es | Qty | Unit Price | | Amount |
| M PIECE-RR | BUMPER : | SIDE, LHEM/ | | | | 1.00 | | 20.00 | 12.80 |
| M MOULDING | ASSY-RR | BUMPER SIDE, L | cut 1 | | | 1.00 | | 20.00 | 16.00 |
| M SENSOR A | SSY-PARK | ING ASSIST SYS | scr | | | 1.00 | 135.00 | | 108.00 108.00 |
| | | ING ASSIST SYS | X | | | 1.00 | | 20.00 | 8.00 |
| M CLIP ive | | | | | | 10.00 | 1.00 | 20.00 | 0.00 |
| | LKK Auto | Consultants hence | natifu | | | | | | |
| | the Repa | nirer of the following | : nothy | ` | | | | | |
| 1 | To resurve | ey before/after spray pai | nting | | | | | | |
| | To display | y damaged part(s) during | resurve | \sim $^{\prime}$ | | $\sqrt{\Gamma}$ | | | |
| 1 | Parts pric Third part | es are subject to confirm ty survey is on a "Withou | Drawd | 21 | :ima | 17516 | 7] | | |
| 1 | No illegal | modification(s) is allowed | tr 16,00.0 | J) (C | , (0 | 11510 | ラ | | |
| | Suppleme | entary item(s) must be re | surveyed | | | | | | |
| | is subject | to final approval from In. | surance (| Company | | | | | |
| 1 | Acknowledg | ged by Repairer | | | | | | | |
| | Signature: | | | #1. | | | | | |
| | Date: | | | ļ | 70 - 40° | Boninser | | 1 | |
| | | | SURVE | YOR NAME | =: Rome-40° | | | 1 | |
| | | | | YOR SIGN | ATLIDE: | | | 1 | |
| | | | SURVE | TOR SIGN | Li Dona | 06/10/20 | wplyy | , | |
| | | | DATE: | | 4 C(ccy) | 00/00/20 | | 1 | |
| | | | | | y | | | | |
| | | | REMAR | RKS: —— | | | | | |
| | | | | | | | | | |
| | | | | (| lak Lahre | paint | | | |
| | | | | | Roby Se fore | • | | | |
| | | | | | 9 | | | | |
| | | | | | | | | 1 | |
| | | | | | | | | | 2 |
| Confirm & a | ccepted ! | by | | | | | | | |
| | | | | | | | Ne | tt | 4,385. |

Nett 4,385.60 7% GST on 4385.60 306.99

Total Payable 4,692.59

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.