

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG20010665/T1ES3Q2  
**Date:** 19/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900256402
<b>Claimant Vehicle No :</b>	SLN40T	<b>Insured Vehicle No :</b>	SMR296P
Date of Loss:	02/10/2020	Nature of Claim:	TP
		Claim No:	8196518702SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLN40T</b>	Engine No:	HIDDEN
Make & Model:	BMW 528I, 2.0 D/AB 2WD 4DR GAS/D NAV (A)	Chassis No:	WBAXG32070DX83316
Reg. Date:	07/12/2012 (Man. Year: 2012)	Odometer:	84934 km
Colour:	Grey		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	16,522.85	14,401.75	2,121.10	12.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,662.00	9,482.90	3,179.10	25.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>29,184.85</b>	<b>23,884.65</b>	<b>5,300.20</b>	<b>18.16</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,042.94</b>	<b>1,671.93</b>	<b>371.01</b>	<b>18.16</b>

<b>Nett Amount (S\$)</b>	<b>31,227.79</b>	<b>25,556.58</b>	<b>5,671.21</b>	<b>18.16</b>
<b>+ Car Rental (8.0 x S\$120.00/day + 7.00% GST) (S\$)</b>		1,027.20		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>26,585.78</b>		

INSPECTION

Date of Assignment: 05/10/2020

Date Inspected: 05/10/2020

Estimated Period of Repair: 9.0 days

Inspected At:

Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby Performance Centre  
Singapore 159941**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*LH ENGINE HOOD HINGE	Bent	93.20 FS	*93.20 FS
3	1		*FRT LH 1 SIDE PANEL BRACKET	Bent	35.10 FS	*35.10 FS
4	1		*FRT LH FENDER	Bent	888.85 FS	*888.85 FS
5	1		*BONNET	Bent	2,336.85 FS	*2,336.85 FS
6	1		*SET OF MOUNT FOR BUMPER	Not Necessary	33.55 FS	*- FS
7	1		*FRT BUMPER CARRIER	Bent	719.50 FS	*719.50 FS
8	1		*FRT BUMPER TOP IMPACT ABSORBER	Cracked	60.00 FS	*60.00 FS
9	1		*FRT BUMPER LH SPACER	Deformed	26.25 FS	*26.25 FS
10	1		*FRT BUMPER LH FINISHER ROD	Not Necessary	37.65 FS	*- FS
11	1		*FRT BUMPER TRIM PRIMED (PDC)	Torn	1,351.15 FS	*1,351.15 FS
12	1		*FRT BUMPER BOTTOM MOUNT (M)	Not Necessary	165.50 FS	*- FS
13	1		*LH GRILLE CHROME	Cracked	141.45 FS	*141.45 FS
14	2		*EMBLEM GROMMET	Not Necessary	1.70 FS	*- FS
15	1		*BMW EMBLEM 82MM	Necessary	71.60 FS	*71.60 FS
16	1		*BOWDEN CABLE FRONT	Not Necessary	41.65 FS	*- FS
17	1		*LEFT GATE	Not Necessary	75.15 FS	*- FS
18	1		*LH LOCK BONNET PASSIVE	Bent	189.55 FS	*189.55 FS
19	1		*BOWDEN CABLE REAR	Not Necessary	41.65 FS	*- FS
20	1		*BOWDEN GAS STRUT	Not Necessary	142.45 FS	*- FS
21	1		*LH SUPPORT	Not Necessary	30.80 FS	*- FS
22	1		*CONNECTION TOP FRT	Bent	163.60 FS	*163.60 FS
23	1		*CONNECTION TOP REAR	Not Necessary	220.80 FS	*- FS
24	1		*LH HEADLAMP SUPPORT	Deformed	221.85 FS	*221.85 FS
25	1		*FRT LH COVER REAR WHEELHOUSE	Not Necessary	128.85 FS	*- FS
26	1		*FRT LH WHEEL ARCH COVER	Deformed	128.85 FS	*128.85 FS
27	1		*COVER LEFT	Deformed	5.45 FS	*5.45 FS
28	1		*LH COVER BOTTOM	Not Necessary	71.30 FS	*- FS
29	1		*SEAL BONNET REAR	Not Necessary	50.75 FS	*- FS
30	1		*FRT LH LOCATOR SEAL	Necessary	228.60 FS	*228.60 FS
31	1		*SEAL ENGINE BONNET FRT	Not Necessary	39.05 FS	*- FS
32	1		*WIRING SET PDC FRONT	Not Necessary	159.50 FS	*- FS
33	1		*HOSE LINE HEADLIGHT CLEANING SYSTEM	Torn	76.10 FS	*76.10 FS
34	1		*LH HIGH PRESSURE NOZZLE	Cracked	184.70 FS	*184.70 FS
35	1		*LAMP HOLDER FOR XENON LAMP	Not Necessary	13.10 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*LH HEADLIGHT GASKET	Not Necessary	34.10 FS	*- FS
37	1		*SET HEADLIGHT GASKET	Necessary	34.85 FS	*34.85 FS
38	1		*GUIDE STRIP WITH SPRING LEFT	Not Necessary	57.90 FS	*- FS
39	1		*LH BI-XENON HEADLIGHT	Cracked	2,662.90 FS	*2,662.90 FS
40	1		*HEADLIGHT DRIVER MOD AHL XENON LIGH	Cracked	840.10 FS	*840.10 FS
41	1		*CONTROL UNIT XENON LIGHT	Cracked	867.85 FS	*867.85 FS
42	1		*REPAIR KIT LED MODULE	Cracked	525.05 FS	*525.05 FS
43	1		*REPAIR KIT HOLDER HEADLIGHT LH	Not Necessary	295.65 FS	*- FS
44	1		*LH FOG LIGHT	Cracked	283.30 FS	*283.30 FS
45	2		*BLIND RIVET	Necessary	2.70 FS	*2.70 FS
46	2		*BLIND RIVET	Necessary	2.70 FS	*2.70 FS
47	5		*HEX BOLT	Necessary	7.50 FS	*7.50 FS
48	1		*RH ENGINE HOOD HINGE	Bent	93.20 FS	*93.20 FS
49	1		*FRT LH 2 SIDE PANEL BRACKET	Bent	35.10 FS	*35.10 FS
50	1		*FRT LH 3 SIDE PANEL BRACKET	Bent	35.10 FS	*35.10 FS
51	1		*LH LEVER	Bent	8.80 FS	*8.80 FS
52	2		*STABILIZER PIN	Bent	2.10 FS	*2.10 FS
53	1		*SUPPORT	Necessary	18.15 FS	*18.15 FS
54	1		*SUPPORT	Bent	18.15 FS	*18.15 FS
55	3		*RIVET	Necessary	1.50 FS	*1.50 FS
56	1		*LH UPPER LOCK SECTION	Bent	68.95 FS	*68.95 FS
57	1		*RH UPPER LOCK SECTION	Bent	68.95 FS	*68.95 FS
58	1		*BONNET CATCH OPERATOR	Bent	41.65 FS	*41.65 FS
59	1		*BRACKET LH	Cracked	11.80 FS	*11.80 FS
60	1		*LH AIR CHANNEL	Deformed	51.80 FS	*51.80 FS
61	1		*REPAIR KIT SOCKET HOUSING 12 POL	Distorted	104.15 FS	*104.15 FS
62	1		*HORN HIGH PITCH	Cracked	89.00 FS	*89.00 FS
63	1		*INSERT DIRECTION INDICATOR LH	Distorted	397.80 FS	*397.80 FS
64	1		*BULB XENON LIGHT W/IGNITION ELEMENT	Cracked	422.85 FS	*422.85 FS
65	1		*NOTICE SAFETY CATCH	Necessary	24.50 FS	*24.50 FS
66	1		*STICK ON LABEL XENON LIGHT	Necessary	24.50 FS	*24.50 FS
67	1		*COATING	Not Necessary	480.00 FS	*- FS
68	1		*AIR DUCT	Necessary	584.10 FS	*584.10 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$)****16,522.85****14,401.75**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE BUMPER FRONT COVER ,BONNET ,FRONT LEFT SIDE PANEL FRONT WALL AND ATTACHMENTS .TO REMOVE AND INSTALL FRONT LEFT DOOR ,FRONT RIGHT SIDE PANEL AND ATTACHMENTS	New	6,375.00	3,825.00
2	TO SPRAY PAINT BUMPER FRONT COVER ,FRONT LEFT SIDE PANEL,BONNET ,FRONT LEFT DOOR AND FRONT RIGHT SIDE PANEL	New	4,991.00	4,491.90
3	TO REPLACE LEFT HEADLIGHT AND REPROGRAMMING	New	481.00	432.00
4	TO TOW ACCIDENT VEHICLE TO PML WORKSHOP	New	195.00	195.00
5	TO REPLACE FRONT PDC SENSOR WIRE HARNESS INCLUDING RESET AND CHECKS FOR PROPER FUNCTION	New	266.00	239.00
6	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
7	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
			<b>Gross Labour Cost (S\$)</b>	<b>12,662.00</b>
				<b>9,482.90</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >