

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20010667/AVF3E2**Date:** 05/07/2021**REFERENCE**

Insured/Claimant:	GUO YA-WEN	Policy No:	2070138029	
Date of Loss:	28/09/2020	Nature of Claim:	OD	Claim No: 5464735119SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU1088B	Engine No:	DKY013858
Make & Model:	AUDI A6, 2.0 (A)	Chassis No:	WAUZZZF26LN056216
Reg. Date:	24/09/2020 (Man. Year: 2020)	Odometer:	100 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$185,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,977.40	15,640.08	23,337.32	59.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,732.00	3,302.00	5,430.00	62.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	47,709.40	18,942.08	28,767.32	60.30
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	46,109.40	17,342.08	28,767.32	62.39
+ GST 7.00/7.00% (S\$)	3,227.66	1,213.95	2,013.71	62.39
Nett Amount (S\$)	49,337.06	18,556.03	30,781.03	62.39

INSPECTION

Date of Assignment:	05/10/2020	
Date Inspected:	05/10/2020	Inspected At: 24 BENOI SECTOR
Estimated Period of Repair:	7.0 days	Repairer : Premium Automobiles Pte Ltd

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	2,763.00 FS	*2,210.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	643.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - CENTRE	Cracked	220.00 FS	*175.60 FS
4	2		*FRONT BUMPER ADAPTER - LH / RH	Damaged	78.00 FS	*61.76 FS
5	1		*FRONT BUMPER REINFORCEMENT - RH	Not Necessary	110.00 FS	*- FS
6	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	151.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT - LOWER	Not Necessary	208.00 FS	*- FS
8	1		*FRONT SPOILER	Not Necessary	249.00 FS	*- FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cracked	429.00 FS	*343.20 FS
10	1		*FRONT BUMPER AIR GUIDE - RH UPPER	Cracked	28.00 FS	*22.32 FS
11	1		*FRONT BUMPER AIR GUIDE - RH LOWER	Cracked	21.00 FS	*16.08 FS
12	1		*RADIATOR GRILLE	Cracked	2,192.00 FS	*1,753.60 FS
13	1		*RADIATOR GRILLE COVER	Not Necessary	54.00 FS	*- FS
14	1		*CONNECTOR HOUSING BRACKET - LH	Not Necessary	28.00 FS	*- FS
15	1		*FRONT BUMPER CARRIER	Not Necessary	960.00 FS	*- FS
16	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	223.00 FS	*178.40 FS
17	2		*FRONT BUMPER SUPPORT	Not Necessary	59.00 FS	*- FS
18	1		*FRONT BUMPER GUIDE SECTION - RH	Damaged	44.00 FS	*34.72 FS
19	1		*FRONT BUMPER BRACKET - RH	Damaged	54.00 FS	*42.72 FS
20	1		*FRONT BUMPER COVER	Cracked	124.00 FS	*99.20 FS
21	1		*CAUTION SIGN STICKER	Necessary	14.00 FS	*10.80 FS
22	1		*OIL COMPLY STICKER	Not Necessary	20.00 FS	*- FS
23	1		*FRONT PARKING AID SENSOR (2PCS)	Damaged (1Pc Only)	386.40 FS	*193.20 FS
24	4		*FRONT PARKING AID SEAL RING	Necessary	14.00 FS	*10.88 FS
25	1		*SET FRONT BUMPER WIRING	Snapped	571.00 FS	*456.40 FS
26	1		*HORN - RH	Not Necessary	214.00 FS	*- FS
27	1		*SPRING SHACKLE - RH	Not Necessary	47.00 FS	*- FS
28	1		*FRONT FENDER - RH	Distorted	1,451.00 FS	*1,160.80 FS
29	1		*FRONT FENDER BRACE - RH	Bent	117.00 FS	*93.60 FS
30	1		*FRONT FENDER BRACKET - RH UPPER	Not Necessary	43.00 FS	*- FS
31	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	42.00 FS	*- FS
32	1		*WHEEL HOUSING LINER - RH	Torn	264.00 FS	*210.80 FS
33	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	70.00 FS	*- FS
34	1		*WHEEL SPOILER - RH	Not Necessary	164.00 FS	*- FS
35	1		*STONE CHIP GUARD - RH	Necessary	50.00 FS	*39.92 FS
36	1		*FENDER TRIM LOWER BRACKET - RH	Not Necessary	40.00 FS	*- FS
37	1		*BONNET	Not Necessary	5,466.00 FS	*- FS
38	1		*BONNET ATTACHMENT PARTS	Not Necessary	230.00 FS	*- FS
39	2		*BONNET LID HINGE - LH / RH	Not Necessary	340.00 FS	*- FS
40	1		*BONNET IMPACT PROTECTION - LH	Not Necessary	19.00 FS	*- FS
41	1		*BONNET IMPACT PROTECTION - RH	Not Necessary	20.00 FS	*- FS
42	1		*BONNET IMPACT PROTECTION - CENTRE	Not Necessary	44.00 FS	*- FS
43	2		*BONNET LID LOCK	Damaged	407.00 FS	*162.80 FS
44	1		*BONNET BOWDEN CABLE - CENTRE	Damaged	57.00 FS	*45.52 FS
45	1		*BONNET RELEASE ELEMENT	Bent	57.00 FS	*45.52 FS
46	1		*BONNET RELEASE LEVER	Not Necessary	13.00 FS	*- FS
47	2		*HEADLIGHT MOUNTING - LH / RH	Not Necessary	234.00 FS	*- FS
48	1		*LED HEADLIGHT - LH / RH	O/S Cut	16,864.00 FS	*6,745.60 FS
49	2		*LIFT CYLINDER - LH / RH	Not Necessary	392.00 FS	*- FS
50	1		*LIFT CYLINDER HOSE	Not Necessary	175.00 FS	*- FS
51	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	76.00 FS	*- FS
52	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	30.00 FS	*- FS
53	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Missing	429.00 FS	*343.20 FS
54	1		*FRONT ALUMINIUM RIM - RH	Cut	990.00 FS	*791.60 FS
55	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SUNDRIES	Necessary	300.00 FS	*2.64 FS
57	2		*BONNET STRIKER - LH / RH	Not Necessary	218.00 FS	*- FS
58	1		*ADAPTER CABLE LOOM FOR FRONT CAMERA (Supplementary)	Damaged	411.00 FS	*328.80 FS
					Total Parts (\$\$)	38,977.40 15,640.08

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT	New	280.00	0.00
2	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
3	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES	New	800.00	250.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND BOTH HEADLIGHTS. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,200.00	1,000.00
5	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND RHS FRONT FENDER	New	3,500.00	1,100.00
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			8,732.00	3,302.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >