

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG20010668/GVD3E2

**Date:** 07/10/2020

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** FBP8089J

**Insured Vehicle No :** SLV6682J

Date of Loss: 29/09/2020

Nature of Claim: TP

Claim No: 6784086654SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBP8089J**

Make & Model: YAMAHA GDR155A (AEROX), 155cc

Engine No: G3J8E0104791

Reg. Date: 11/06/2019 (Man. Year: 2019)

Chassis No: MH3SG4640KJ055898

Colour: Black

Odometer: 0 km

Engine Capacity: 155 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: 120/80-14

Rear Tyre Size: 150/70-14

Front Left Side: MITAS 6 mm

Rear Left Side: MITAS 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment: 02/10/2020

Date Inspected: 05/10/2020 Inspected At:

HI Cycle Pte Ltd (HQ)  
AUTOBAY @ KAKI BUKIT, 1 KAKI BUKIT  
AVE 6 #02-58  
Singapore 417883

Estimated Period of Repair: 2.0 days

**Adjuster:** XING GUO QIANG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WING MIRROR	Cut	0.00 F	*- F
2	1		*HANDLE BAR	Bent	0.00 F	*- F
3	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F
4	1		*CLUTCH LEVER	Cut	0.00 F	*- F
5	1		*SIDE FAIRING	Cut	0.00 F	*- F
6	1		*FAIRING LOWER	Cut	0.00 F	*- F
7	1		*STEP BOARD	Cut	0.00 F	*- F
8	1		*RADIATOR	Cut	0.00 F	*- F
9	1		*SIDE STAND	Cut	0.00 F	*- F
10	1		*MAIN STAND	Cut	0.00 F	*- F
11	1		*CLUTCH ENGINE COVER	Cut	0.00 F	*- F
12	1		*EXHAUST MUFFLER HEAT SHIELD	Cut	0.00 F	*- F
13	1		*EXHAUST MUFFLER ASSY	* Check	0.00 F	*- F
14	1		*REAR BOX	Cut	0.00 F	*- F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**