



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 939M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BENT / TORN	2,235.00	2,235.00
1	REAR BUMPER LOWER LID	BENT	2,175.00	2,175.00
1	REAR BUMPER TOWING COVER	DENTED	55.25	55.25
1	REAR BUMPER REFLECTOR RH	CRACKED	57.00	57.00
1	REAR BUMPER REINFORCEMENT	BENT	895.00	895.00
16	RIVET @\$5.25	NECESSARY	84.00	84.00
1	RH EXHAUST DIP	BENT	390.00	390.00
1	REAR EXHAUST MUFFLER	* CHECK	2,450.00	-
1	SET REAR PARKING SENSOR	MISSING	187.20	187.20
1	RH TAILLAMP	BROKEN	615.45	615.45
1	RH TAILLAMP HOLDER	CRACKED	12.25	12.25
1	REAR BOOT	BENT	1,820.00	1,820.00
2	REAR BOOT HINGES @\$280.00	* CHECK	560.00	-
1	REAR BOOT LOCK	TO REPAIR SEE LABOUR	510.00	-
1	REAR BOOT WEATHERSTRIP	DISTORTED	217.50	217.50
1	REAR BOOT LAMP RH	CRACKED	905.00	905.00
1	REAR BOOT LOGO	NECESSARY	131.25	131.25
1	REAR BOOT EMBLEM - GIULIA	NECESSARY	135.50	135.50
1	REAR RH FENDER INNER TRIM	DEFORMED	935.00	935.00
1	REAR END PANEL	BENT	1,505.00	1,505.00
1	REAR END PANEL TOP COVER	MTG DISTORTED	301.00	301.00
1	FRONT BUMPER	CRACKED	2,430.00	2,430.00
1	FRONT BUMPER BRACKET RH UPPER	* CHECK	22.06	-
1	FRONT BUMPER BRACKET RH RETAINER	DISTORTED	48.65	48.65
1	FRONT BUMPER RH AIR GUIDE	DISTORTED	144.50	144.50
1	RH HEADLAMP	MTG CRACKED	6,621.50	6,621.50
1	RH HEADLAMP WASHER	CRACKED	826.00	826.00
1	RH HEADLAMP WASHER CAP	MISSING	62.00	62.00
1	FRONT RH FENDER	BUCKLED	1,260.00	1,260.00
1	FRONT RH FENDER INNERSHIELD	DISTORTED	332.50	332.50

Report Ref No. CS/UOI20010674/Kvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT RH FENDER BRACE BRACKET	* CHECK	157.50	-
1	RH BUMPER GRILLE	* CHECK	114.95	-
1	FRONT BUMPER SPONGE	* CHECK	136.50	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	1,290.00	-
1	REAR BUMPER RETAINER RH (ADDITIONAL)	CRACKED	40.00	40.00
1	REAR BUMPER BRACKET RH (ADDITIONAL)	BENT	143.50	143.50
1	REAR BUMPER BRACKET CTR (ADDITIONAL)	BENT	257.50	257.50
1	RH TAILLAMP PANEL (ADDITIONAL)	BENT	367.50	367.50
	LESS 20% DISCOUNT		-6,086.21	-5,038.01
			24,344.85	20,152.04
	LABOUR			
	TO CHECK WIRING AND LIGHTING.		60.00	40.00
	TO SUPPLY PANEL SEALANT AND TO SEAL OFF ALL WELD SPOT SEAMS AND GAPS.		90.00	60.00
	TO REMOVE AND REFIT REAR TRIMS AND UPHOLSTERY.		120.00	60.00
	TO INSTALL REVERSE SENSOR AND REAR VIEW CAMERA.		150.00	80.00
	TO SPRAY RUBBERIZED UNDER COATING.		120.00	60.00
	TO REMOVE AND REFIT EXHAUST MUFFLER.		80.00	60.00
	TO KNOCK JACKOUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF REAR BOOT LOCK AND FRONT BUMPER REINFORCEMENT.		1,600.00	1,000.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		1,600.00	1,200.00
			3,820.00	2,560.00
	GRAND TOTAL		28,164.85	22,712.04
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$2,752.81 NETT)			22,712.04

Report Ref No. CS/UOI20010674/Kvd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.