



**GOLDBELL**  
ENGINEERING

Industrial Vehicles  
20,000 Served, And Counting

**GOLDBELL ENGINEERING PTE LTD**

10 Tuas Avenue 18 Singapore 638894

Tel. +65 6861 0007 Fax. +65 6861 3676 (Sales)

Fax +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co Reg No 198003963G

**INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	SBB9955B
Policy No:	DMPCBN30767719000	Date of Loss:	21/09/2019
Vehicle Reg. No.:	<b>SBB9955B</b>	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	VISA SG HOLDING	Contact No:	+6594888998
Make/Model:	LEXUS GS250, 2.5 PREMIUM (GRL11R) (A)	Vehicle Reg. Date:	30/01/2013
Vehicle Colour:	WHITE	Chassis No:	JTHBF1BL905005977
Engine No:	4GR0853860		
Odometer:	112516 KM		
Paint Type:			
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	28		
Present Location:	GOLDBELL ENGINEERING PTE LTD (TUAS)		

**COST OF CLAIMS**

	<b>Amount</b>
Parts	38,554.00
Miscellaneous Items	5,246.00
Labour	5,610.00
Paintwork Labour	2,400.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>51,810.00</b>
<b>+ GST 7.00% (S\$)</b>	<b>3,626.70</b>
<b>Nett Amount (S\$)</b>	<b>55,436.70</b>

**This claim is handled by: SOO LEONG KEAT**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**TAILS**

**Source:** MRM-SG

Version: 1.0 (Last Synchronised: 02 Oct 2020)

**Plate:** 143

LEXUS GS250 2.5 Premium (GRL11R) (A) (Catalogue Merimen Singapore 1.0)

**Labour:** Repairer's

(Price-denominated Standard List)

**Print Code:** Goldbell Engineering Pte Ltd/SBB9955B/02/10/2020 14:43

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER / CAA	0.00	0.00	*396.00 F
2	2		*FRONT BUMPER RETAINER	0.00	0.00	*108.00 F
3	1		*FRONT BUMPER REINFORCEMENT ?	0.00	0.00	*228.00 F
4	1		*FRONT BUMPER OUTER GARNISH / CAA	0.00	0.00	*90.00 F
5	1		*FRONT BUMPER LOWER GRILLE / M.S.	0.00	0.00	*84.00 F
6	2		*FRONT BUMPER FOG LAMP X NN	0.00	0.00	*216.00 F
7	1		*FRONT BUMPER UNDERCOVER / M.S.	0.00	0.00	*348.00 F
8	1		*FRONT NOZZLE ?	0.00	0.00	*228.00 F
9	1		*FRONT NOZZLE COVER X NN	0.00	0.00	*12.00 F
10	1		*FRONT GRILLE / CAA	0.00	0.00	*396.00 F
11	1		*FRONT GRILLE CHROME GARNISH X NN	0.00	0.00	*168.00 F
12	1		*FRONT GRILLE EMBLEM / MCC	0.00	0.00	*174.00 F
13	2		*FRONT HEADLAMP ?	0.00	0.00	*3,240.00 F
14	2		*FRONT HEADLAMP SUPPORT ?	0.00	0.00	*384.00 F
15	1		*SUPPORT PANEL UPPER ?	0.00	0.00	*168.00 F
16	1		*SUPPORT PANEL LOWER ?	0.00	0.00	*138.00 F
17	1		*SUPPORT PANEL TOP GARNISH ?	0.00	0.00	*168.00 F
18	1		*BONNET X Repair	0.00	0.00	*960.00 F
19	2		*BONNET HINGE X	0.00	0.00	*84.00 F
20	1		*BONNET INSULATOR X } NN	0.00	0.00	*174.00 F
21	1		*BONNET RUBBER X	0.00	0.00	*80.00 F
22	2		*FRONT FENDER / Buc. ?	0.00	0.00	*768.00 F
23	2		*FRONT FENDER AIR DUCT ?	0.00	0.00	*204.00 F
24	2		*FRONT FENDER INNER SHIELD / Re.	0.00	0.00	*288.00 F
25	1		*FRONT WHEELHOUSE LH X Repair.	0.00	0.00	*576.00 F
26	1		*FRONT DOOR PANEL LH X } Repair.	0.00	0.00	*780.00 F
27	1		*REAR DOOR PANEL LH X	0.00	0.00	*576.00 F
28	1		*SIDE SKIRT LH / Cut	0.00	0.00	*284.00 F
29	1		*REAR FENDER LH X Repair	0.00	0.00	*540.00 F
30	1		*REAR FENDER INNER SHIELD LH X NN	0.00	0.00	*114.00 F
31	1		*REAR BUMPER X Repair.	0.00	0.00	*420.00 F
32	1		*REAR BUMPER RETAINER X NN	0.00	0.00	*48.00 F
33	1		*EXHAUST MUFFLER LH ?	0.00	0.00	*420.00 F
34	1		*EXHAUST MUFFLER RH ?	0.00	0.00	*540.00 F
35	1		*EXHAUST MID PIPE ?	0.00	0.00	*1,020.00 F
36	1		*STEERING RACK ?	0.00	0.00	*2,760.00 F
37	2		*FRONT ABS SENSOR X NN	0.00	0.00	*708.00 F
38	2		*FRONT SHOCK ABSORBER ?	0.00	0.00	*552.00 F
39	2		*FRONT KNUCKLE ARM ?	0.00	0.00	*552.00 F
40	2		*FRONT LOWER ARM ?	0.00	0.00	*960.00 F
41	2		*FRONT UPPER ARM ?	0.00	0.00	*840.00 F

Goldbell Engineering Pte Ltd/SBB9955B/02/10/2020 14:43. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

Repairer Estimates

	Quantity	Particulars	%Disc	%Depr	Amount
		*FRONT BRAKE CALIPER X	0.00	0.00	*864.00 F
		*FRONT BRAKE DISC X	0.00	0.00	*468.00 F
		*FRONT BRAKE SENSOR X	0.00	0.00	-
		*LINKAGE ?	0.00	0.00	*156.00 F
		*ANTI-ROLL BAR ?	0.00	0.00	*144.00 F
		*FRONT CROSSMEMBER ?	0.00	0.00	*780.00 F
		*REAR LOWER ARM ?	0.00	0.00	*456.00 F
		*REAR KNUCKLE ARM ?	0.00	0.00	*840.00 F
		*REAR KNUCKLE ARM BEARING ?	0.00	0.00	*600.00 F
		*REAR SHOCK ABSORBER ?	0.00	0.00	*340.00 F
		*REAR ABS SENSOR X	0.00	0.00	*708.00 F
		*REAR BRAKE CALIPER X	0.00	0.00	*2,760.00 F
		*REAR BRAKE SENSOR X	0.00	0.00	-
		*REAR BRAKE DISC X	0.00	0.00	*444.00 F
		*DRIVE SHAFT ?	0.00	0.00	*4,560.00 F
		*LONG SHAFT ?	0.00	0.00	*3,240.00 F
		*REAR CROSSMEMBER ?	0.00	0.00	*1,440.00 F
		<b>Total Parts (S\$)</b>			<b>38,554.00</b>

F=Franchise part.

Goldbell Engineering Pte Ltd/SBB9955B/02/10/2020 14:43. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

on Miscellaneous Items  
 Particulars

Amount

Miscellaneous Items		Amount
1	BONNET INSULATOR CLIPS /	30.00
2	1 BRAKE FLUID /	100.00
3	1 FRONT BUMPER CLIPS /	20.00
4	4 FRONT BUMPER SENSOR /	696.00
5	2 FRONT FENDER INNER SHIELD CLIPS /	60.00
6	1 FRONT GRILLE CLIPS /	30.00
7	1 FRONT NUMBER PLATE /	80.00
8	1 FRONT NUMBER PLATE HOLDER X NN	80.00
9	1 LH SIDE SKIRT CLIPS / MCL	60.00
10	2 REAR FENDER INNER SHIELD CLIPS X NN	60.00
11	1 SUPPORT PANEL TOP GARNISH CLIPS / MCL	30.00
12	4 TYRE 3 pcs / Cart	2,400.00
13	2 TYRE RIM / Cart	1,600.00
<b>Sub Total (S\$)</b>		<b>5,246.00</b>

Estimates on Labour

Particulars	Lab.Type	Amount
<b>Paintwork Labour</b>		
1 SPRAY PAINTING ON AFFECTED AREAS	New	1700 <del>1600</del> 2,400.00
<b>Labour Items</b>		
2 CHECK WIRING AND LIGHTNING SYSTEM	New	30 60.00
3 REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	New	? 200.00
4 REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS	New	? 200.00
5 COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT	New	60 150.00
6 COMPUTERISED AND CHECK REAR WHEEL ALIGNMENT	New	60 200.00
7 REMOVE AND REPLACE BONNET FROM OLD TO NEW	New	X 150.00
8 REMOVE AND REPLACE FRONT DOOR PANEL	New	X 200.00
9 REMOVE AND REPLACE REAR DOOR PANEL	New	X 200.00
10 REMOVE AND REFIT REAR QUARTER GLASS TO FACILITATE REPAIR	New	X 300.00
11 REMOVE, RENEW AND REFIT FRONT SENSOR	New	40 200.00
12 REMOVE, RENEW AND REFIT EXHAUST	New	? 200.00
13 REMOVE AND REFIT FUEL TANK TO FACILITATE REPAIR	New	X 500.00
14 MOUNT VEHICLE ON BENCH FOR CHASSIS ALIGNMENT	New	X 500.00
15 PANEL BEATING ON AFFECTED AREAS	New	800 2,400.00
16 APPLY ANTI RUST ON AFFECTED AREAS	New	60 150.00
<b>Gross Labour Cost (S\$)</b>		<b>8,010.00</b>

Goldbell Engineering Pte Ltd/SBB9955B/02/10/2020 14:43. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

8 Days -

Leapsun Repair.  
After repair photos.

Not Authorised.

Kuo Qiang  
8288 0282

06/10/2020.

Excess \$500.



**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: