

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3361C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BROKEN	459.40	459.40
10	REAR BUMPER COVER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER REINFORCEMENT BRACKET LH	NOT NECESSARY	138.10	-
1	REAR BUMPER SIDE BRACKET LH	BROKEN	55.80	55.80
1	REAR BUMPER TOWING COVER	NOT NECESSARY	98.80	-
1	REAR BUMPER REFLECTOR LAMP LH	CUT	31.90	31.90
1	REAR BUMPER CENTRE MOULDING ASSY	CUT	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING ASSY	NOT NECESSARY	155.00	-
	LESS 20% DISCOUNT		-282.45	-204.07
			1,129.80	816.28
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN)	NOT NECESSARY	180.00	-
			180.00	-
	<u>LABOUR</u>			
	PANEL BEATING.		450.00	320.00
	SPRAY PAINTING.		300.00	200.00
	REMOVE / REPLACE REVERSE SENSOR.		120.00	30.00
	TUFF KOTE.	NOT NECESSARY	90.00	-
	CHECK LIGHTING.		60.00	30.00
			1,020.00	580.00
	GRAND TOTAL		2,329.80	1,396.28

RECOMMENDED COST OF REPAIRS (CONFIRMED)	1,396.28

Report Ref No. NS/INC20010679/Etd3e2



**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**