

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 8205Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BROKEN	458.60	458.60
1	REAR BUMPER UNDER COVER	CUT	552.60	552.60
1	REAR REINFORCEMENT STAY ARM RH	NOT NECESSARY	139.60	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	318.80	-
10	BUMPER CLIPS	NECESSARY	22.00	22.00
2	REAR BUMPER SIDE RETAINER LH / RH	BROKEN	112.70	112.70
1	TAIL LAMP UPPER RH	BROKEN	557.90	557.90
1	TAIL LAMP LOWER RH	BROKEN	548.40	548.40
1	REFLECTOR RH	NOT NECESSARY	31.90	-
1	TOWING COVER	NOT NECESSARY	82.70	-
	LESS 25% DISCOUNT		-706.30	-563.05
			2,118.90	1,689.15
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
1	REAR RH FENDER ADVERTISEMENT (SN)	NECESSARY	100.00	100.00
1	REAR BUMPER ADVERTISEMENT (SN)	NECESSARY	50.00	50.00
1	EMBLEM HYBRID (SN)	NECESSARY	52.30	52.30
1	EMBLEM PRIUS (SN)	NECESSARY	52.30	52.30
1	LOGO COMFORTDELGRO STICKER (SN)	NECESSARY	30.00	30.00
1	LOGO COMFORT TEL NO STICKER (SN)	NECESSARY	30.00	30.00
1	LOGO COMFORT APP STICKER (SN)	NECESSARY	40.00	40.00
			490.30	354.60
	<u>LABOUR</u>			
	PANEL BEATING.		700.00	320.00
	SPRAY PAINTING.		600.00	400.00
	WIRING.		60.00	30.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
	REMOVE / REFIX REVERSE SENSOR.		60.00	30.00
			1,480.00	780.00

Report Ref No. NS/INC20010680/Esd3e2





GRAND TOTAL	4,089.20	2,823.75

RECOMMENDED COST OF LUMP SUM REPAIRS		2,250.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		·

Report Ref No. NS/INC20010680/Esd3e2



Automotive Assessor

1

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser