

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20010684/UBA3Q2

Date: 08/12/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
Claimant Vehicle No :	SLU6561E	Insured Vehicle No :	GBK3079Y
Date of Loss:	03/10/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0001974

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU6561E		
Make & Model:	HYUNDAI TUCSON, 1.6 GLS T-GDI DCT 2WD (A)	Engine No:	G4FJHU336905
Reg. Date:	11/12/2017 (Man. Year: 2017)	Chassis No:	KMHJ3812VJU628238
Colour:	Grey	Odometer:	30101 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,989.00	3,448.00	6,541.00	65.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	1,220.00	910.00	42.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,119.00	4,668.00	7,451.00	61.48
+ GST 7.00/7.00% (S\$)	848.33	326.76	521.57	61.48
Nett Amount (S\$)	12,967.33	4,994.76	7,972.57	61.48
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,502.21		
Global Sum Settlement (S\$)		5,400.00		

INSPECTION

Date of Assignment: 12/10/2020

Date Inspected: 12/10/2020 Inspected At:

Hock Wah Motor Workshop Pte Ltd
(Bedok)
Blk 3011, Bedok Industrial Park E.,
#01-2008/2010/2012
Singapore 489977

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Nov 2020)
Parts:	M1-SUV	HYUNDAI TUCSON 1.6 GLS T-GDI DCT 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU6561E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE WIPER MOTOR	Not Necessary	415.00 F	*- FL
2	1		*TAILGATE	Badly Dented	1,028.00 F	*1,028.00 FL
3	1		*TAILGATE LAMP RH	Cracked	871.00 F	*825.00 FL
4	1		*TAILGATE LAMP LH	Cracked	871.00 F	*825.00 FL
5	1		*TAILGATE EMBLEM	Necessary	29.00 F	*29.00 FL
6	1		*TAILGATE LOGO -TUCSON	Necessary	29.00 F	*29.00 FL
7	1		*TAILGATE LOGO -TURBO S	Necessary	57.00 F	*57.00 FL
8	1		*TAILGATE OUTER GARNISH	Deformed / Torn	595.00 F	*595.00 FL
9	1		*TAILGATE TRIMBOARD	Not Necessary	242.00 F	*- FL
10	1		*TAILGATE COVER	Not Necessary	595.00 F	*- FL
11	1		*TAILGATE WEATHERSTRIP	Not Necessary	126.00 F	*- FL
12	1		*TAILGATE LOCK	Not Necessary	677.00 F	*- FL
13	1		*TAILGATE ABSORBER RH	Not Necessary	1,009.00 F	*- FL
14	1		*TAILGATE ABSORBER LH	Not Necessary	1,009.00 F	*- FL
15	1		*REAR BUMPER	Deformed / Cut	446.00 F	*446.00 FL
16	1		*REAR BUMPER RETAINER RH	Not Necessary	25.00 F	*- FL
17	1		*REAR BUMPER RETAINER LH	Not Necessary	25.00 F	*- FL
18	1		*REAR BUMPER REINFORCEMENT	Not Necessary	271.00 F	*- FL
19	1		*REAR BUMPER BRACKET RH	Not Necessary	25.00 F	*- FL
20	1		*REAR BUMPER BRACKET LH	Not Necessary	25.00 F	*- FL
21	1		*REAR BUMPER CENTER GARNISH	Cut	334.00 F	*334.00 FL
22	1		*REAR BUMPER GARNISH RH (RH) (NPA)	Not Necessary	0.00 F	*- FL
23	1		*REAR BUMPER GARNISH RH (LH) (NPA)	Not Necessary	0.00 F	*- FL
24	4		*REVERSE SENSOR	Serviceable	560.00 F	*- FL
25	2		*WINDSCREEN SEALANT	Necessary	48.00 FS	*40.00 FS
26	1		*REVERSE CAMERA	Serviceable	580.00 FS	*- FS
27	1		*END PANEL (NPA)	Repair	0.00 FS	*- FS
28	1		*REAR NUMBER PLATE HOLDER	Scratched	30.00 FS	*20.00 FS
29	1		*TAILGATE UPPER GARNISH MOULDING	Cracked	67.00 F	*67.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,989.00	4,295.00
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	847.00
Total Parts (\$)	9,989.00	3,448.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	800.00	500.00
2	SPRAYPAINT ON THE AFFECTED AREAS	New	800.00	500.00
3	ANTI-RUST COATING	New	120.00	30.00
4	TO REMOVE & REFIT WINDSCREEN	New	180.00	120.00
5	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
6	WIRING	New	80.00	20.00
Gross Labour Cost (\$)			2,130.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >