

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20010688/AGS3Q2

**Date:** 19/11/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SMJ6554Y	<b>Insured Vehicle No :</b>	SHA7272K
Date of Loss: 25/09/2020	Nature of Claim: TP	Claim No: MCT20090429

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMJ6554Y</b>		
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Engine No:	LEB7104024
Reg. Date:	14/03/2019 (Man. Year: 2018)	Chassis No:	GP72003043
Colour:	Red	Odometer:	62404 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,325.92	2,441.60	1,884.32	43.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	1,300.00	1,880.00	59.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,505.92</b>	<b>3,741.60</b>	<b>3,764.32</b>	<b>50.15</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>7,505.92</b>	<b>3,000.00</b>	<b>4,505.92</b>	<b>60.03</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment:	05/10/2020	
Date Inspected:	07/10/2020 Inspected At:	Leang Automotive (HQ) BLK 1 KAKI BUKIT AVE 6 #02-12 AUTOBAY@ KAKI BUKIT Singapore 417883
Estimated Period of Repair:	4.0 days	

**Adjuster:** ADRIAN LING

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 19 Nov 2020)	
<b>Parts:</b>	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMJ6554Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,350.60 FL	*1,150.00 FL
2	2		*REAR BUMPER SIDE HOLDER	Necessary	53.00 FL	*53.00 FL
3	2		*REAR BUMPER SIDE COVER	Not Necessary	90.00 FL	*- FL
4	2		*REAR BUMPER SIDE COVER REFLECTOR	Not Necessary	96.00 FL	*- FL
5	2		*REAR BUMPER SIDE SPONGE	Not Necessary	179.00 FL	*- FL
6	1		*REAR END PANEL	Repair	560.80 FL	*- FL
7	1		*REAR END PANEL TOP GARNISH	Not Necessary	155.50 FL	*- FL
8	1		*REAR END PANEL ANTENNA SENSOR	Not Necessary	85.00 FL	*- FL
9	1		*TAILGATE	Dented	1,193.00 FL	*1,193.00 FL
10	1		*TAILGATE LOCK	Not Necessary	187.50 FL	*- FL
11	1		*TAILGATE WEATHERSTRIPE	Not Necessary	168.50 FL	*- FL
12	1		*TAILGATE INNER TRIM BOARD	Not Necessary	320.00 FL	*- FL
13	1		*TAILGATE GLASS MOULDING	Necessary	125.00 FL	*125.00 FL
14	1		*HONDA LOGO	Necessary	38.50 FL	*38.50 FL
15	1		*SHUTTLE EMBLEM	Necessary	55.00 FL	*55.00 FL
16	1		*HYBRID EMBLEM	Necessary	75.00 FL	*75.00 FL
17	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
18	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
19	1		*SET REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
20	1		*SET TAILGATE TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
21	1		*TAILGATE GLASS SEALANT	Necessary	100.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,272.40</b>	<b>2,979.50</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	946.48	537.90
<b>Total Parts (\$\$)</b>	<b>4,325.92</b>	<b>2,441.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING REMOVE AND REFIT PARTS	New	1,200.00	400.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	500.00
3	WIRING CHECK	New	50.00	30.00
4	TUFF COAT	New	150.00	60.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	60.00
7	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
8	TO REMOVE AND REFIT TAILGATE GLASS	New	180.00	120.00
<b>Gross Labour Cost (S\$)</b>			<b>3,180.00</b>	<b>1,300.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**