

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Oct 2020 Edit Reg		06 Oct 2020 00:00 Edit Adj Rpt	S\$2,600.00 Edit Estimates	S\$2,600.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	TAN SOK HUANG, ID: S1482705F		
Main Claimant:	DZUL' ADLY BIN ZAINAL ABIDIN, ID: S7737836G		
Vehicle Reg. No.:	SMQ7788X	Date of Loss:	03/10/2020 00:00 - :59 [11 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1102745482SG	Policy/Cover Note No.:	2100502627 (Comprehensive)
Vehicle Reg. No. (Insured):	SLL4893H	Policy No. (Claimant):	
		Excess:	
Repairer:	Kaizen Motors Pte Ltd (HQ) 68 KAKI BUKIT AVE 6, #02-12 ARK @ KAKI BUKIT, 417896 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Yong, Joanne] Joanne-LF.yong@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 15/10/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (09/10/2020): [Request to upload TP GIA Report](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SMQ7788X (1102745482SG)**
[SLL4893H]

TP

DZUL' ADLY BIN ZAINAL ABIDIN

Oct 3 2020 12:00AM

[TAN SOK HUANG]

Kaizen Motors Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View
[View in Browser](#)

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	09/10/20 07:29	Video - Accident	Load MP4	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/10/20 08:03	Chassis Number	Load JPG	☒
2	10/10/20 08:03	Odometer Reading	Load JPG	☒
3	10/10/20 08:04	General View	Load JPG	☒
4	10/10/20 08:04	General View	Load JPG	☒
5	10/10/20 08:04	General View	Load JPG	☒
6	10/10/20 08:04	General View	Load JPG	☒
7	10/10/20 08:04	General View	Load JPG	☒
8	10/10/20 08:04	General View	Load JPG	☒
9	10/10/20 08:04	General View	Load JPG	☒
10	10/10/20 08:04	General View	Load JPG	☒
11	10/10/20 08:04	General View	Load JPG	☒
12	10/10/20 08:04	General View	Load JPG	☒
13	10/10/20 08:04	General View	Load JPG	☒
14	10/10/20 08:04	General View	Load JPG	☒
15	10/10/20 08:04	General View	Load JPG	☒
16	10/10/20 08:04	General View	Load JPG	☒
17	10/10/20 08:04	General View	Load JPG	☒
18	10/10/20 08:04	General View	Load JPG	☒
19	10/10/20 08:04	General View	Load JPG	☒
20	10/10/20 08:04	General View	Load JPG	☒
21	10/10/20 08:04	General View	Load JPG	☒
22	10/10/20 08:04	General View	Load JPG	☒
23	10/10/20 08:04	General View	Load JPG	☒
24	10/10/20 08:04	General View	Load JPG	☒
25	10/10/20 08:04	General View	Load JPG	☒
26	10/10/20 08:04	General View	Load JPG	☒
27	10/10/20 08:04	General View	Load JPG	☒
28	10/10/20 08:04	General View	Load JPG	☒
29	10/10/20 08:04	General View	Load JPG	☒
30	10/10/20 08:04	General View	Load JPG	☒
31	10/10/20 08:04	General View	Load JPG	☒
32	10/10/20 08:04	General View	Load JPG	☒

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
33	12/10/20 07:55	After Repair Photo		Load JPG ☒
34	12/10/20 07:55	After Repair Photo		Load JPG ☒
35	12/10/20 07:55	After Repair Photo		Load JPG ☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	09/10/20 10:32	TP GIA REPORT		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	09/10/20 07:14	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG20010707/UVF3S2**Date:** 15/10/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100502627
Claimant Vehicle No :	SMQ7788X	Insured Vehicle No :	SLL4893H
Date of Loss:	03/10/2020	Nature of Claim:	TP
		Claim No:	1102745482SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ7788X		
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Engine No:	2ZR0E32334
Reg. Date:	08/10/2019 (Man. Year: 2019)	Chassis No:	ZWR800404194
Colour:	White	Odometer:	81062 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,713.10	2,325.50	3,387.60	59.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,520.00	980.00	3,540.00	78.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,233.10	3,305.50	6,927.60	67.70
Approved Total (Overridden) (\$\$)		2,600.00		
(\$\$)	10,233.10	2,600.00	7,633.10	74.59
+ GST 7.00/7.00% (\$\$)	716.32	182.00	534.32	74.59
Nett Amount (\$\$)	10,949.42	2,782.00	8,167.42	74.59

INSPECTION

Date of Assignment:	06/10/2020	
Date Inspected:	08/10/2020	Inspected At: Kaizen Motors Pte Ltd (HQ) 68 KAKI BUKIT AVE 6, #02-12 ARK @ KAKI BUKIT Singapore 417896
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

10/15/2020

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY	Cut	1,053.20 F	*1,053.20 FL
2	1		*FRONT R/H FENDER ASSY	Repair	980.40 F	*- FL
3	1		*FRONT R/H SIDE MIRROR ASSY	Broken	1,055.30 F	*1,055.30 FL
4	1		*FRONT R/H SIDE MIRROR COVER	Missing	350.30 F	*165.10 FL
5	1		*FRONT R/H SIDE MIRROR GLASS	Broken	180.40 F	*180.40 FL
6	1		*FRONT R/H DOOR ASSY	Repair	1,320.20 F	*- FL
7	1		*FRONT R/H DOOR SEAL	Not Necessary	203.30 F	*- FL
8	10		*FRONT BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
9	10		*FRONT FENDER CLIPS	Not Necessary	35.00 FS	*- FS
10	1		*FRONT R/H RIM	Cut	500.00 FS	*450.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,713.10	2,939.00
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	613.50
Total Parts (\$\$)	5,713.10	2,325.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR CHECKING ON WIRING.	New	120.00	20.00
2	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS, INCLUDING WELDING, KNOCKING, REPAIRING, STRAIGHTENING, RESHAPE & ADJUSTMENT OF FRONT BUMPER, FENDER, SIDE MIRROR.	New	2,700.00	300.00
3	SPRAY PAINTING & PUTTY OF BUMPER, FENDER SIDE MIRROR.	New	1,200.00	600.00
4	APPLYING OF RUST-PROOFING.	New	250.00	0.00
5	LABOUR FOR WHEEL ALIGNMENT.	New	250.00	60.00
Gross Labour Cost (\$\$)			4,520.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >