

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20010708/DQF3Q2

Date: 04/01/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 30001551758

Claimant
Vehicle No : SHA2172Z

Insured Vehicle No : SMJ8170H

Date of Loss: 04/10/2020

Nature of Claim: TP

Claim No: 248881

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA2172Z**

Make & Model: HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)

Engine No: G4LEKU401745

Reg. Date: 07/11/2019 (Man. Year: 2019)

Chassis No: KMHC851CVLU187924

Colour: Blue

Odometer: 99428 km

Engine Capacity: 1580 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: DURATURN 6 mm

Rear Left Side: DURATURN 6 mm

Front Right Side: DURATURN 6 mm

Rear Right Side: DURATURN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,957.19	9,136.52	10,820.67	54.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,410.00	2,320.00	3,090.00	57.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	25,367.19	11,456.52	13,910.67	54.84
+ GST 7.00/7.00% (\$\$)	1,775.70	801.96	973.74	54.84
Nett Amount (\$\$)	27,142.89	12,258.48	14,884.41	54.84

INSPECTION

Date of Assignment: 07/10/2020

Date Inspected: 06/10/2020 Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)

Blk 9 Sector C, #01-42 Sin Ming

Industrial Estate

Singapore 575644

Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jan 2021)
Parts:	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA2172Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR (RH)	Bent	1,797.20 FL	*1,797.20 FL
2	1		*FRT DOOR RUBBER	Necessary	250.00 FL	*250.00 FL
3	1		*FRONT DOOR REGULATOR (RH)	Not Necessary	750.40 FL	*- FL
4	1		*FRONT DOOR OUTER HANDLE (RH)	Repair	234.80 FL	*- FL
5	1		*FRONT DOOR TRIM BOARD (RH)	Not Necessary	796.80 FL	*- FL
6	1		*FRONT DOOR OUTER MOULDING (RH)	Cut/Distorted	110.10 FL	*110.10 FL
7	1		*REAR DOOR (RH)	Bent	1,789.90 FL	*1,789.90 FL
8	1		*REAR DOOR RUBBER (RH)	Necessary	270.00 FL	*270.00 FL
9	1		*REAR DOOR OUTER MOULDING (RH)	Cut/Distorted	125.30 FL	*125.30 FL
10	1		*REAR DOOR GEAR/REGULATOR (RH)	Not Necessary	367.84 FL	*- FL
11	1		*REAR DOOR POWER MOTOR (RH)	Not Necessary	256.80 FL	*- FL
12	1		*REAR DOOR HINGE UPPER (RH)	Not Necessary	173.88 FL	*- FL
13	1		*REAR DOOR HINGE LOWER (RH)	Not Necessary	170.50 FL	*- FL
14	1		*REAR DOOR CHECK (RH)	Not Necessary	85.92 FL	*- FL
15	1		*REAR DOOR TRIM BOARD (RH)	Not Necessary	613.60 FL	*- FL
16	1		*REAR DOOR PROTECTOR (RH)	Not Necessary	166.20 FL	*- FL
17	1		*DOOR CENTRE PILLAR OUTER (RH)	Not Necessary	3,764.90 FL	*- FL
18	1		*ROCKER PANEL OUTER GARNISH	Cut	715.60 FL	*715.60 FL
19	1		*ROCKER PANEL OUTER	Not Necessary	1,799.60 FL	*- FL
20	1		*REAR BUMPER	Cut	459.40 FL	*459.40 FL
21	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
22	1		*REAR FENDER (RH)	Dented	1,768.30 FL	*1,768.30 FL
23	1		*ASSY BSD BLIND SPOT RADAR (RH)	Not Necessary	1,625.00 FL	*- FL
24	1		*REAR TYRE RIM (RH)	Distorted	1,124.20 FL	*1,124.20 FL
25	1		*REAR WHEEL HUP-CAP (RH)	Cut	346.40 FL	*346.40 FL
26	1		*REAR WHEELBEARING & HUB ASSY	Damaged	554.00 FL	*554.00 FL
27	1		*REAR TRAILING ARM (RH)	Distorted	265.40 FL	*265.40 FL
28	1		*REAR ASSIST (RH)	Distorted	227.90 FL	*227.90 FL
29	1		*REAR SHOCK ABSORBER (RH)	Distorted	230.50 FL	*230.50 FL
30	1		*REAR SHOCK ABSORBER MOUNTING (RH)	Not Necessary	133.10 FL	*- FL
31	1		*REAR ABSORBER STOPPER (RH)	Not Necessary	137.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
32	1		*REAR ABSORBER COVER (RH)	Not Necessary	175.60 FL	*- FL
33	1		*REAR CROSSMEMBER	Not Necessary	1,468.70 FL	*- FL
34	1		*STABILIZER BAR	Not Necessary	387.30 FL	*- FL
35	1		*STABILIZER LINK (RH)	Not Necessary	147.30 FL	*- FL
36	1		*REAR UPPER ARM (RH)	Distorted	239.50 FL	*239.50 FL
37	1		*REAR LOWER ARM (RH)	Distorted	393.10 FL	*393.10 FL
38	1		*REAR KNUCKLE ARM (RH)	Distorted	538.10 FL	*538.10 FL
39	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (RH)	Necessary	80.00 FS	*80.00 FS
40	1		*REAR TYRE (RH)	Not Necessary	216.00 FS	*- FS
41	1		*FRONT DOOR COMFORT LOGO (RH)	Necessary	75.00 FS	*75.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					24,853.74	11,381.90
- List Item Discount on L Items 20.00/20.00% (\$\$)					4,896.55	2,245.38
Total Parts (\$\$)					19,957.19	9,136.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,600.00	900.00
2	SPRAY PAINTING CHARGE	New	1,400.00	900.00
3	WIRING CHARGE	New	140.00	0.00
4	TUFF KOTE	New	160.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX UNDERCARRIAGE (RR)	New	400.00	150.00
7	RE-SET REAR ABS SYSTEM	New	400.00	0.00
8	TRANSFER OF DOOR MECHANISM FRONT	New	80.00	60.00
9	RE-SET FRT POWER WINDOW SYSTEM	New	200.00	0.00
10	TRANSFER OF DOOR MECHANISM REAR	New	80.00	60.00
11	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
12	FOUR WHEEL ALIGNMENT	New	120.00	60.00
13	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	150.00
Gross Labour Cost (\$)			5,410.00	2,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >