Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20010710/KQF3Q2

Date: 02/11/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A80463249QMK Claimant SJT502U

Insured Vehicle No: SGH6555B Vehicle No:

Date of Loss: Nature of Claim: ΤP 03/10/2020 Claim No: 629392

DESCRIPTION & IDENTIFICATION OF VEHICLE

SJT502U Reg No:

Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 2NR5433657

Chassis No: Reg. Date: 21/09/2020 (Man. Year: 2020) MR2B23F3901202909

3665 km Colour: Metallic Grey Odometer:

Engine Capacity: 1496 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15 Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 9 mm Front Right Side: Rear Right Side: Yokohama 9 mm Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	337.50	337.50	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	750.00	600.00	150.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,087.50	937.50	150.00	13.79
+ GST 7.00/7.00% (S\$)	76.13	65.63	10.50	13.79
Nett Amount (S\$)	1,163.63	1,003.13	160.50	13.79

INSPECTION

06/10/2020 Date of Assignment:

Date Inspected: 19/10/2020 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun

Industrial Park A Singapore 768761

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Reference			
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Oct 2020)	
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	: (Unsubmitted, no print-code for SJT502U)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.			

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	429.00 FL	*429.00 FL
2	6		*FRONT BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
F=Franchise part. L=ListItemDisc.						
				Sub Total (S\$)	450.00	450.00
- List Item Discount on L Items 25.00/25.00% (S\$)			112.50	112.50		
				Total Parts (S\$)	337.50	337.50
			Dan ant was was who	nitted during this print-out.		

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REMOVE & REFIX FRT BUMPER ASSY ,GRILLE ,FOG LAMP & GARNISH ,LOWER GRILLE ,KNOCK & REPAIR FRT RH FENDER & REALIGN THE SAME	New	300.00	200.00
2	PUTTY & RESPRAY ON FRT RH FENDER ,FRT BUMPER	New	450.00	400.00
	Gross Labou	ır Cost (S\$)	750.00	600.00
	Renort was unsubmitted duri	na this print-out		

< END OF ESTIMATES >