



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2103040

INV Date 29/04/2021

Reference CC4/FCI20010711/Aes3q2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SKJ 7434C

Insured Veh. SHA 8329A

Claim No. D20003985MFSH

Policy No. D-20094921MFSH

Accident Date 30/09/2020

Inspection Date 06/10/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20010711/Aes3q2	
			Date: 29/04/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 8329A	Veh. Inspected	SKJ 7434C
	Policy No.	D-20094921MFSH	Coverage (\$)	0.00
	Claim No.	D20003985MFSH	Excess (\$)	0.00
	Assign From	ERIC	Assign Date	06/10/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	JTFST22P100014177	Colour	WHITE
	Odometer	258261 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	MAXXIS	6 mm
	L/H Front Tyre	195 R15C	MAXXIS	6 mm
	R/H Rear Tyre	195 R15C	MAXXIS	6 mm
	L/H Rear Tyre	195 R15C	MAXXIS	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/09/2020	Inspection Date	06/10/2020
	Survey held at	CAS GARAGE PTE LTD NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKJ 7434C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILGATE	NOT NECESSARY	1,650.90	-
1	REAR TAILGATE LOGO	NOT NECESSARY	78.90	-
1	REAR TAILGATE WINDSCREEN INNER SEAL	NOT NECESSARY	50.00	-
1	TAILGATE OUTER GARNISH	NOT NECESSARY	192.30	-
1	TAILGATE INNER LOCK	NOT NECESSARY	461.60	-
1	TAILGATE LOCK CATCH	NOT NECESSARY	42.00	-
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	381.90	-
2	TAILGATE SIDE STOPPER (INNER) @\$36.00	NOT NECESSARY	72.00	-
2	TAILGATE SIDE STOPPER (OUTER) @\$39.00	NOT NECESSARY	78.00	-
1	TAILAMPS	O/S CRACKED	385.90	385.90
1	TAILAMPS INNER SEALER	NECESSARY	40.00	20.00
1	TAILAMP PANEL	NOT NECESSARY	385.70	-
1	REAR BUMPER	DEFORMED	456.30	456.30
1	REAR CORNER PANEL RH	DEFORMED	185.90	185.90
1	REAR BUMPER SIDE RETAINERS	O/S NECESSARY	75.20	75.20
1	REAR BUMPER STAYS	NOT NECESSARY	38.50	-
1	REAR BUMPER	NOT NECESSARY	781.40	-
1	END PANEL INNER	NOT NECESSARY	994.80	-
1	END PANEL TOP PLATE	NOT NECESSARY	185.90	-
1	END PANEL OUTER	NOT NECESSARY	426.50	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	987.60	-
1	REAR FENDER AIR DUCTS	NOT NECESSARY	75.80	-
1	REAR FENDER COVERS	NOT NECESSARY	65.80	-
2	REAR MUDFLAPS @\$45.80	NOT NECESSARY	91.60	-
	LESS 25% DISCOUNT		-2,046.13	-280.83
			6,138.37	842.47
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	30.00	30.00
2	SET REAR TAILAMPS CLIPS @\$30.00 (SN)	NECESSARY	60.00	20.00
2	SET REAR BUMPER ALUMINIUM PROTECTOR (SN)	NOT NECESSARY	700.00	-

Report Ref No. CC4/FCI20010711/Aes3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	50.00	-
1	SET REAR FENDER CUSTOMIZED STICKERS (SN)	NECESSARY	650.00	350.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
1	SET REAR TAILGATE CUSTOMIZED STICKER (SN)	NOT NECESSARY	700.00	-
1	REAR BUMPER STEP BAR (SN)	NOT NECESSARY	700.00	-
1	SET END PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
1	SET REVERSE SENSORS (SN)	NOT NECESSARY	250.00	-
			3,470.00	600.00
	LABOUR			
	TO RENEW ,REPAIR ,REALIGN ,DAMAGED PARTS ,REPLACE ,BET AND WELD .INCLUSIVE OF THE REPAIR OF REAR FENDER RH .		2,000.00	400.00
	TO RESPRAY AFFECTED AREAS.		2,000.00	350.00
	TO TUFFCOAT AFFECTED AREA.		200.00	50.00
	TO REMOVE/REFIT REAR INTERIOR UPHOLSTERY .	NOT NECESSARY	180.00	-
	TO CONDUCT WIRING CHECK AND ADJUST REAR TAILLAMPS.		120.00	30.00
	TO REMOVE AND REPLACE REAR SENSORS AND DISTANCE SETTLING.		180.00	50.00
	TO REMOVE /REFIT AND REPLACE TAILGATE MECHANISM .	NOT NECESSARY	180.00	-
			4,860.00	880.00
GRAND TOTAL			14,468.37	2,322.47

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,800.00
---	--	--	-----------------

Report Ref No. CC4/FCI20010711/Aes3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKJ 7434C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

