

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20010712/R1QF3E2
Date: 06/01/2021

REFERENCE

Insured/Claimant: JACKSON LIM JEK SHENG Policy No: 1900263052
Date of Loss: 06/10/2020 Nature of Claim: OD Claim No: 1351811091SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGC5802X**
Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGKH749375
Reg. Date: 06/01/2020 (Man. Year: 2019) Chassis No: KNAF5416MK5052314
Colour: Grey Odometer: 16836 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$82,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm
Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,929.60	9,541.20	3,388.40	26.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,290.00	4,140.00	1,150.00	21.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,219.60	13,681.20	4,538.40	24.91
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	17,919.60	13,381.20	4,538.40	25.33
+ GST 7.00/7.00% (S\$)	1,254.37	936.68	317.69	25.33
Nett Amount (S\$)	19,173.97	14,317.88	4,856.09	25.33

INSPECTION

Date of Assignment: 06/10/2020
Date Inspected: 06/10/2020 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CARRIER ASSY-FRONT END MODULE	Cracked	675.00 FL	*675.00 FL
2	1		*BRACKET ASSY - FENDER & BUMPER, R	Serviceable	9.00 FL	*- FL
3	1		*BRACKET ASSY - FENDER & BUMPER, L	Serviceable	9.00 FL	*- FL
4	1		*BEAM COMPLETE - FR BUMPER	Bent	497.00 FL	*497.00 FL
5	1		*CONDENSER ASSY - COOLER	Bent	687.00 FL	*687.00 FL
6	1		*GUARD - AIR, LH	Cracked	28.00 FL	*28.00 FL
7	1		*GUARD - AIR, RH	Cracked	28.00 FL	*28.00 FL
8	1		*RADIATOR ASSY	Bent	646.00 FL	*646.00 FL
9	1		*BLOWER ASSY	Serviceable	656.00 FL	*- FL
10	1		*LAMP ASSY - HEAD, LH	Broken	2,210.00 FL	*2,210.00 FL
11	1		*LAMP ASSY - HEAD, RH	Cracked	2,210.00 FL	*2,210.00 FL
12	1		*HINGE ASSY - HOOD, RH	Bent	43.00 FL	*43.00 FL
13	1		*HINGE ASSY - HOOD, LH	Bent	43.00 FL	*43.00 FL
14	1		*PANEL ASSY - HOOD	Bent	1,502.00 FL	*1,502.00 FL
15	1		*PANEL - FENDER, LH	Bent	430.00 FL	*430.00 FL
16	1		*INSULATOR - FENDER LH	Serviceable	27.00 FL	*- FL
17	1		*PANEL - FENDER, RH	Repair	430.00 FL	*- FL
18	1		*PAD - HOOD INSULATOR	Deformed	156.00 FL	*156.00 FL
19	1		*LATCH ASSY - HOOD	Serviceable	103.00 FL	*- FL
20	10		*CLIP - HOOD INSULATING PAD MTG	Necessary	10.00 FL	*10.00 FL
21	1		*ORNAMENT - KIA NO. 115	Necessary	32.00 FL	*32.00 FL
22	1		*BRACKET - FR BUMPER UPR SIDE MTG	Serviceable	22.00 FL	*- FL
23	1		*BRACKET - FR BUMPER UPR SIDE MTG	Serviceable	22.00 FL	*- FL
24	1		*STIFFNER - FR BPR LWR	Serviceable	114.00 FL	*- FL
25	1		*ABSORBER - FRONT BUMPER ENERGY	Cracked	84.00 FL	*84.00 FL
26	1		*AIR DUCT - FR BUMPER, LH	Serviceable	14.00 FL	*- FL
27	1		*AIR DUCT - FR BUMPER, RH	Serviceable	14.00 FL	*- FL
28	1		*LAMP ASSY - SIDE REPEATER, LH	Cracked	143.00 FL	*143.00 FL
29	1		*LAMP ASSY - SIDE REPEATER, RH	Not Necessary	143.00 FL	*- FL
30	1		*MOULDING - FRONT BUMPER, LH	Cracked	216.00 FL	*216.00 FL
31	1		*MOULDING - FRONT BUMPER, RH	Serviceable	216.00 FL	*- FL
32	1		*GARNISH - RADIATOR GRILLE	Cracked	38.00 FL	*38.00 FL
33	1		*GRILLE ASSY - RADIATOR	Cracked	328.00 FL	*328.00 FL
34	1		*COVER - FR BUMPER	Cracked	633.00 FL	*633.00 FL
35	4		*GRILLE - FRONT BUMPER	Cracked	1,940.00 FL	*485.00 FL
36	1		*CAP - FRONT HOOK	Cut	9.00 FL	*9.00 FL
37	2		*RETAINER - BUMPER SIDE MTG	Serviceable	2.00 FL	*- FL
38	1		*LAMP ASSY - FRONT FOG, LH	Serviceable	303.00 FL	*- FL
39	1		*LAMP ASSY - FRONT FOG, RH	Serviceable	303.00 FL	*- FL
40	1		*COVER - FR BUMPER FOG LAMP, LH	Serviceable	15.00 FL	*- FL
41	1		*COVER - FR BUMPER FOG LAMP, RH	Serviceable	15.00 FL	*- FL
42	1		*WIRING ASSY - BUMPER EXTENSION	Cut	207.00 FL	*207.00 FL
43	1		*ULTRASONIC SENSOR ASSY - P.A.S	Distorted	163.00 FL	*163.00 FL
44	1		*ULTRASONIC SENSOR ASSY - P.A.S	Distorted	163.00 FL	*163.00 FL
45	1		*ULTRASONIC SENSOR ASSY - P.A.S	Serviceable	163.00 FL	*- FL
46	1		*ULTRASONIC SENSOR ASSY - P.A.S	Serviceable	163.00 FL	*- FL
47	1		*HORN ASSY - LOW PITCH	Cracked	74.00 FL	*74.00 FL
48	1		*FRONT NUMBER PLATE WITH FRAME	Bent	50.00 FS	*50.00 FS
49	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
50	1		*DUCT-EXTENSION	Cracked	5.00 FL	*5.00 FL
51	1		*BUZZER ASSY-PIEZO	Cracked	68.00 FL	*68.00 FL
52	1		*COOLANT (4L)	Necessary	26.00 FL	*26.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,137.00	11,909.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,207.40	2,367.80
Total Parts (\$\$)	12,929.60	9,541.20

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, LH FRONT FENDER, RH FRONT FENDER	New	2,000.00	1,200.00
2	REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER	New	100.00	100.00
3	TOP UP A/CON GAS AND CHECK A/CON SYSTEM	New	80.00	80.00
4	REMOVE AND INSTALL PARKING ASSIST	New	60.00	60.00
5	PAINT WORK SPRAY FRONT BONNET, FRONT BUMPER, LH FRONT FENDER, LH FRONT DOOR, RH FRONT FENDER AND AFFECTED PORTION	New	2,100.00	1,750.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.	New	120.00	120.00
7	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
8	REPLACE FRONT CARRIER & REPAIR RH FRONT FENDER.	New	800.00	800.00
Gross Labour Cost (S\$)			5,290.00	4,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >