LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18007359/GQF3

Date: 16/12/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: S28789335SMF

Claimant Vehicle SLS8312E Insured Vehicle No: SLD514X

No:

Date of Loss: 19/04/2018 Nature of Claim: TP Claim No: 556058

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS8312E

 Make & Model:
 MERCEDES-BENZ \$350, 3.5 CGI (A)
 Engine No:
 27695030010957

 Reg. Date:
 30/11/2011 (Man. Year: 2011)
 Chassis No:
 WDD2211572A407947

Colour: Black Odometer: 129935 km

Engine Capacity: 3498 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/45 R18 Rear Tyre Size: 255/45 R18
Front Left Side: General 8 mm Rear Left Side: General 8 mm
Front Right Side: General 8 mm Rear Right Side: General 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		8,345.00	2,665.00	5,680.00	68.06
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,415.00	565.00	850.00	60.07
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	9,760.00	3,230.00	6,530.00	66.91
	+ GST 7.00/7.00% (S\$)	683.20	226.10	457.10	66.91
	Nett Amount (S\$)	10,443.20	3,456.10	6,987.10	66.91

INSPECTION

Date of Assignment: 07/09/2020

Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E,, #01-

Date Inspected: 09/10/2020 Inspected At: 2008/2010/2012

Singapore 489977

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG Manager: SHIAU CHAN

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Dec 2020)

Parts: 143 MERCEDES-BENZ S350 3.5 CGI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLS8312E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRONT LAMP COVER LH	Serviceable	340.00 F	*- F
2	1	*FRONT DOOR SIDE MIRROR LH	Replaced	1,365.00 F	*1,365.00 F
3	1	*FRONT RIM HUB BEARING LH	Serviceable	680.00 F	*- F
4	1	*FRONT LOWER ARM LH	Serviceable	780.00 F	*- F
5	1	*FRONT SHOCK ABSORBER LH	Serviceable	3,200.00 F	*- F
6	1	*FRONT RIM LH	Replaced	1,300.00 FS	*1,300.00 FS
7	1	*FRONT TYRE LH	Serviceable	680.00 FS	*- FS
8	1	*FRONT FENDER LH (NPA)	Repaired	0.00 FS	*- FS
F=Fra	anchise part. S=SpcNe	tt.	_		
			Total Parts (S\$)	8,345.00	2,665.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	500.00	200.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	500.00	300.00
3	TO REMOVE & REFIT UNDERCARRIAGE	New	350.00	0.00
4	WIRING	New	40.00	40.00
5	TWO WHEEL ALIGNMENT	New	25.00	25.00
		Gross Labour Cost (S\$)	1,415.00	565.00
	Report was unsubn	nitted during this print-out.		

< END OF ESTIMATES >