

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20010721/ASD3E2
Date: 22/12/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSNW00064692000	
Claimant Vehicle No : SJY3805A	Insured Vehicle No : YP9141L	
Date of Loss: 02/10/2020	Nature of Claim: TP	Claim No: SNM20D203686/C02/CHUAKK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY3805A		
Make & Model:	HONDA CITY, 1.5 L I-VTEC (A)	Engine No:	L15A71809448
Reg. Date:	26/08/2010 (Man. Year: 2009)	Chassis No:	MRHGM26509P020415
Colour:	Grey	Odometer:	172470 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,004.52	1,190.88	813.64	40.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,340.00	860.00	480.00	35.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,344.52	2,050.88	1,293.64	38.68
Approved Total (Overridden) (\$\$)		1,600.00		
	3,344.52	1,600.00	1,744.52	52.16
+ GST 7.00/7.00% (\$\$)	234.12	112.00	122.12	52.16
Nett Amount (\$\$)	3,578.64	1,712.00	1,866.64	52.16

INSPECTION

Date of Assignment:	13/10/2020	
Date Inspected:	06/10/2020 Inspected At:	Twincar Automotive Pte Ltd - Kaki Bukit (HQ) 2 KAKI BUKIT AVENUE 2, #01-17 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Dec 2020)
Parts:	143	HONDA CITY 1.5 L I-VTEC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY3805A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ENGINE UNDER COVER CENTER	Torn	32.40 FL	*32.40 FL
2	1		*ENGINE UNDER COVER LH	Torn	45.40 FL	*45.40 FL
3	1		*ENGINE UNDER COVER RH	Torn	45.40 FL	*45.40 FL
4	1		*FRONT BUMPER	Distorted	459.80 FL	*459.80 FL
5	1		*FRONT FENDER INNER SHIELD L/R	O/S Torn	148.80 FL	*74.40 FL
6	1		*FRONT GRILLE	Cracked	109.90 FL	*109.90 FL
7	1		*FRONT GRILLE LOGO EMBLEM	Necessary	23.40 FL	*23.40 FL
8	1		*FRONT GRILLE OUTER COVER	Cracked	152.30 FL	*152.30 FL
9	1		*FRONT HEADLAMP L/R	O/S Cracked	696.20 FL	*348.10 FL
10	1		*FRONT HEADLAMP LOWER BRACKET L/R	O/S Cracked	70.40 FL	*35.20 FL
11	1		*FRONT RH FENDER	Repair	290.60 FL	*- FL
12	1		*FRONT WASHER TANK	Deformed	62.30 FL	*62.30 FL
13	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
14	1		*FRONT BUMPER NUMBER PLATE	Not Necessary	25.00 FS	*- FS
15	1		*FRONT BUMPER NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
16	2		*SET FRONT FENDER INNER SHIELD CLIPS L/R	Necessary	100.00 FS	*30.00 FS
17	1		*SET FRONT GRILLE CLIPS	Necessary	40.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,431.90	1,468.60
- List Item Discount on L Items 20.00/20.00% (\$)	427.38	277.72
Total Parts (\$)	2,004.52	1,190.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSING. (TO FR)	New	80.00	30.00
2	TO RE-SPRAY PAINTING ON THE CHANGE BODY PARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	700.00	400.00
3	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	500.00	400.00
4	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	60.00	30.00
Gross Labour Cost (\$\$)			1,340.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >