

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20010722/UPS3Q2

**Date:** 10/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800116825

**Claimant**  
**Vehicle No :** SBY8900U **Insured Vehicle No :** ES555G

Date of Loss: 05/10/2020 Nature of Claim: TP Claim No: 5726435469SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SBY8900U</b>		
Make & Model:	AUDI A1, 999cc SB 1.0 TFSI (PI) (A)	Engine No:	CHZ064019
Reg. Date:	29/02/2016 (Man. Year: 2015)	Chassis No:	WAUZZZ8X0GB067812
Colour:	Blue	Odometer:	43940 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/50R16	Rear Tyre Size:	195/50R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,159.00	5,215.80	943.20	15.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,230.00	1,660.00	570.00	25.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,389.00</b>	<b>6,875.80</b>	<b>1,513.20</b>	<b>18.04</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,500.00</b>		
<b>(S\$)</b>	8,389.00	5,500.00	2,889.00	34.44
<b>+ GST 7.00/7.00% (S\$)</b>	587.23	385.00	202.23	34.44
<b>Nett Amount (S\$)</b>	<b>8,976.23</b>	<b>5,885.00</b>	<b>3,091.23</b>	<b>34.44</b>
<b>+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		535.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>6,422.00</b>		

### INSPECTION

Date of Assignment: 06/10/2020

Date Inspected: 06/10/2020 Inspected At:

Stytech Auto Pte Ltd (HQ)  
2 Kaki Bukit Ave 2 #02-30, Kaki Bukit  
Autohub  
Singapore 417921

Estimated Period of Repair: 5.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Badly Dented	1,550.00 F	*1,550.00 FL
2	1		*REAR BOOT EMBLEM	Necessary	98.00 F	*98.00 FL
3	1		*REAR BOOT A1 WORDING	Necessary	98.00 F	*98.00 FL
4	1		*REAR BOOT TFSI WORDING	Necessary	98.00 F	*98.00 FL
5	2		*REAR BOOT NUMBER PLATE LAMP	Not Necessary	60.00 F	*- FL
6	1		*REAR BOOT LEFT TAILLAMP	Scratched	760.00 F	*760.00 FL
7	1		*REAR BOOT INNER TRIM BOARD	Not Necessary	300.00 F	*- FL
8	1		*REAR BUMPER	Dented	1,145.00 F	*1,145.00 FL
9	1		*REAR BUMPER REINFORCEMENT	Bent	420.00 F	*420.00 FL
10	1		*REAR END PANEL	Dented	500.00 F	*500.00 FL
11	1		*REAR END PANEL GARNISH	Twisted	400.00 F	*400.00 FL
12	1		*WEATHER STRIP	Twisted	400.00 F	*295.00 FL
13	1		*REAR BOOT LOCK	Not Necessary	150.00 F	*- FL
14	1		*REAR NUMBER PLATE	Bent	40.00 FS	*40.00 FS
15	1		*REAR GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
16	1		*REAR BOOT INNER TRIM BOARD CHIPS	Not Necessary	40.00 FS	*- FS
17	1		*REAR BUMPER CHIPS	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,159.00</b>	<b>5,484.00</b>
<b>- List Item Discount on L Items 0.00/5.00% (\$\$)</b>	0.00	268.20
<b>Total Parts (\$\$)</b>	<b>6,159.00</b>	<b>5,215.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
2	TO TRANSFER TAILGATE MECHANISM	New	150.00	60.00
3	ANTI RUST PROOF	New	80.00	60.00
4	CHECK WIRING	New	80.00	20.00
5	PANEL BEATING	New	800.00	600.00
6	TO PUTTY & SPRAY PAINTING	New	1,000.00	800.00
<b>Gross Labour Cost (S\$)</b>			<b>2,230.00</b>	<b>1,660.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**