

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20010737/D3Q2

Date: 30/10/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNA00027412001

Claimant
Vehicle No : SKQ6497RInsured
Vehicle No : SJP3179X

Date of Loss: 01/10/2020

Nature of
Claim: TPClaim
No: SNM20D203664C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKQ6497R**

Make & Model: TOYOTA PREVIA, 2.4 7-seater (A)

Engine No: 2AZJ125070

Reg. Date: 16/12/2014 (Man. Year: 2014)

Chassis No: JTEGD54M90A047028

Colour: Grey

Odometer: 67276 km

Engine Capacity: 2362 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Michelin 7 mm

Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm

Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,642.35	1,428.52	2,213.83	60.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,270.00	1,790.00	480.00	21.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,912.35	3,218.52	2,693.83	45.56
Approved Total (Overridden) (S\$)		2,550.00		
(S\$)	5,912.35	2,550.00	3,362.35	56.87
+ GST 7.00/7.00% (S\$)	413.86	178.50	235.36	56.87
Nett Amount (S\$)	6,326.21	2,728.50	3,597.71	56.87

INSPECTION

Date of Assignment: 05/10/2020

Date Inspected: 19/10/2020

Inspected At:

Ethoz Group (ethoz)
22 TAMPINES ST 92
Singapore 528876

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2020)
Parts:	M1-MPV	TOYOTA PREVIA 2.4 7-seater (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ6497R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,436.20 FL	*- FL
2	1		*TAILGATE WEATHERSTRIPE	Not Necessary	419.30 FL	*- FL
3	1		*TAILGATE LOCK	Not Necessary	435.20 FL	*- FL
4	1		*TAILGATE LOGO	Necessary	74.40 FL	*74.40 FL
5	1		*TAILGATE EMBLEM TOYOTA	Necessary	73.60 FL	*73.60 FL
6	1		*TAILGATE EMBLEM PRVIA	Necessary	72.90 FL	*72.90 FL
7	1		*TAILGATE EMBLEM GL	Necessary	69.40 FL	*69.40 FL
8	1		*REAR FENDER (LH) (NPA)	Repair	0.00 FL	*- FL
9	1		*REAR BUMPER	Distorted	654.20 FL	*654.20 FL
10	1		*REAR BUMPER BRACKET (LH)	Not Necessary	118.90 FL	*- FL
11	1		*REAR BUMPER SIDE RETAINER LH (1)	Not Necessary	108.80 FL	*- FL
12	1		*REAR BUMPER SIDE RETAINER LH (2)	Not Necessary	86.70 FL	*- FL
13	1		*REAR BUMPER SPONGE	Torn	93.40 FL	*93.40 FL
14	1		*REAR BUMPER REFLECTOR LH	Broken	92.80 FL	*92.80 FL
15	1		*REAR BUMPER TOW COVER LH	Twisted	80.90 FL	*80.90 FL
16	10		*REAR BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
17	1		*REAR END PANEL	Badly Dented	648.10 FL	*648.10 FL
18	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
19	1		*REVERSE SENSOR	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,769.80	1,904.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,127.45	476.18
Total Parts (\$\$)	3,642.35	1,428.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO FACILITATE REPAIR	New	900.00	800.00
2	TO DETACH & RENEW REVERSE SENSOR	New	40.00	40.00
3	TO REMOVE & INSTALL REAR WINDSCREEN GLASS	New	140.00	0.00
4	TO REMOVE & INSTALL ALL TAILGATE FITTING	New	100.00	0.00
5	TO APPLY ANTI RUST COATING ON AFFECTED AREAS	New	60.00	30.00
6	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	20.00
7	TO SPRAY PAINT ON AFFECTED AREAS	New	1,000.00	900.00
Gross Labour Cost (\$\$)			2,270.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >