

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20010743/T1VF3E2

Date: 16/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1800108959
Claimant Vehicle No : SGS8228A	Insured Vehicle No : SLN3551R
Date of Loss: 03/10/2020	Nature of Claim: TP Claim No: 6978573758SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGS8228A	
Make & Model:	MERCEDES-BENZ S400 HYBRID, 3.5 (A)	Engine No: 27696030683360
Reg. Date:	02/10/2014 (Man. Year: 2014)	Chassis No: WDD2221572A081823
Colour:	Silver	Odometer: 48672 km
Engine Capacity:	3498 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/50 R18	Rear Tyre Size:	245/50 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	06/10/2020	
Date Inspected:	09/10/2020	Inspected At: TJ Car Care Services (HQ) Blk 1010, #01-115, Bukit Merah Lane 3 Singapore 159724
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REVERSE SENSOR	Not Working	0.00 F	*- F
4	1		*REAR BUMPER REFLECTOR	Cut	0.00 F	*- F
5	1		*REAR BUMPER LOWER	* Check	0.00 F	*- F
6	1		*REAR EXHAUST CHROME TIP	* Check	0.00 F	*- F
7	1		*REAR BUMPER REINFORCEMENT	* Check	0.00 F	*- F
8	1		*REAR BUMPER SPONGE	* Check	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >