

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20010753/EES3Q2
Date: 07/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700063959-03
Claimant Vehicle No :	SH6334E	Insured Vehicle No :	EB81X
Date of Loss:	05/10/2020	Nature of Claim:	TP
		Claim No:	2568393904SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH6334E		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDEU483838
Reg. Date:	22/10/2015 (Man. Year: 2015)	Chassis No:	KMHLB41UMGU079300
Colour:	Blue	Odometer:	663425 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,637.76	2,619.84	17.92	0.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,730.00	1,020.00	710.00	41.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,367.76	3,639.84	727.92	16.67
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	4,367.76	2,900.00	1,467.76	33.60
+ GST 7.00/7.00% (S\$)	305.74	203.00	102.74	33.60
Nett Amount (S\$)	4,673.50	3,103.00	1,570.50	33.60
+ Loss of Use (2.5 x S\$50.00/day) (S\$)		125.00		
+ Car Rental (2.5 x S\$114.95/day) (S\$)		287.38		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,517.38		
Global Sum Settlement (S\$)		3,500.00		

INSPECTION

Date of Assignment:	06/10/2020	
Date Inspected:	06/10/2020	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969

4/7/2021

Adjuster Report

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER W LIP & FOG	Broken	1,052.20 FL	*1,052.20 FL
2	1		*BRKT ASSY -FR BPR UP	Not Necessary	22.40 FL	*- FL
3	1		*BRACKET -FR BUMPER S	Broken	24.60 FL	*24.60 FL
4	10		*HYUNDAI BUMPER COVER CLIP	Necessary	22.00 FL	*22.00 FL
5	1		*PANEL -FENDER LH	Dented	663.00 FL	*663.00 FL
6	1		*LAMP ASSY -HEAD LH	Cut	1,388.00 FL	*1,388.00 FL
7	1		*FRT FENDER ADVERTISEMENT LOGO LH	Necessary	100.00 FS	*100.00 FS
					Sub Total (S\$)	3,272.20 3,249.80
					- List Item Discount on L Items 20.00/20.00% (S\$)	634.44 629.96
					Total Parts (S\$)	2,637.76 2,619.84

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	700.00	560.00
2	SPRAYPAINT ON AFFECTED AREA	New	450.00	400.00
3	CHECK ALL LIGHTING	New	50.00	30.00
4	TUFF COAT ON AFFECTED PARTS	New	530.00	30.00
Gross Labour Cost (S\$)			1,730.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >