

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sur@lkkauto.com](mailto:sur@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

# VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG20010757/T1TF3E2

**Date:** 10/11/2020

### REFERENCE

Insured/Claimant:	MARCUS CHIA SEE WEI	Policy No:	1800091113	
Date of Loss:	05/10/2020	Nature of Claim:	OD	Claim No: 3420934793SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD1960Y				
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)		Engine No:	4J11YP9394	
Reg. Date:	07/08/2018 (Man. Year: 2018)		Chassis No:	GF7W0402085	
Colour:	Grey		Odometer:	28986 km	
Engine Capacity:	1998 cc				
Market Value/New Car Price:	S\$88,000.00				
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>				

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,674.62	3,247.84	1,426.78	30.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	2,300.00	650.00	22.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>7,624.62</b>	<b>5,547.84</b>	<b>2,076.78</b>	<b>27.24</b>
<b>- Excess (\$\$)</b>	600.00	600.00	0.00	0.00
<b>(\$\$)</b>	7,024.62	4,947.84	2,076.78	29.56
<b>+ GST 7.00/7.00% (\$\$)</b>	491.72	346.35	145.37	29.56
<b>Nett Amount (\$\$)</b>	<b>7,516.34</b>	<b>5,294.19</b>	<b>2,222.15</b>	<b>29.56</b>

### INSPECTION

Date of Assignment: 06/10/2020  
Date Inspected: 07/10/2020 Inspected At:

Cycle & Carriage Automotive Pte Ltd  
(Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339

Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*HEADLAMP ASSY, RH	Cracked	2,125.00 FL	*2,125.00 FL
3	1		*FENDER, FR RH	Bent	688.00 FL	*688.00 FL
4	1		*HOOD	Bent	975.00 FL	*975.00 FL
5	1		*HINGE, HOOD, LH	Repair	68.00 FL	*- FL
6	1		*HINGE, HOOD, RH	Repair	68.00 FL	*- FL
7	1		*LATCH, HOOD	Repair	76.00 FL	*- FL
8	1		*ENGINE HOOD EMBLEM	Necessary	80.00 FL	*80.00 FL
9	1		*BRACKET, FR BUMPER SIDE, LH	Not Necessary	18.00 FL	*- FL
10	1		*BRACKET, FR BUMPER SIDE, RH	Not Necessary	18.00 FL	*- FL
11	1		*FACE, FR BUMPER	Not Necessary	859.00 FL	*- FL
12	1		*COVER, FR BUMPER	Not Necessary	294.00 FL	*- FL
13	1		*GARNISH, FR BUMPER, RH	Not Necessary	75.00 FL	*- FL
14	1		*GARNISH, FR BUMPER SIDE	Cut	48.00 FL	*48.00 FL
15	1		*GARNISH, FR BUMPER SIDE	Not Necessary	220.00 FL	*- FL
16	1		*GARNISH, FR BUMPER SIDE	Not Necessary	112.00 FL	*- FL
17	1		*BRKT, FR BUMPER SIDE, LWR RH	Not Necessary	6.00 FL	*- FL
18	1		*MOULDING, FR BUMPER, RH	Deformed	116.00 FL	*116.00 FL
19	1		*MOULDING, FR WHEEL ARCH, RH	Deformed	160.00 FL	*160.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>6,056.00</b>	<b>4,212.00</b>
<b>- List Item Discount on L Items 23.00/23.00% (S\$)</b>	1,381.38	964.16
<b>Total Parts (S\$)</b>	<b>4,674.62</b>	<b>3,247.84</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	RENEW ACCIDENT DAMAGED PARTS ON FRONT BONNET, RH FRONT FENDER, FRONT BUMPER FACE	New	1,350.00	900.00
2	PAINT WORK SPARY FRONT BONNET, RH FRONT FENDER AND AFFECTED PORTION	New	1,050.00	1,050.00
3	APPLY BODY SEALANT	New	80.00	0.00
4	RE-APPLY ZERTONA BODY COATING	New	240.00	160.00
5	PERFORM RUST PREVENTION	New	80.00	40.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM 0.60	New	30.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>2,950.00</b>	<b>2,300.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >