Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20010758/KYD3E2

Date: 19/10/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No: GBH4535G

Date of Loss: 30/09/2020 Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKW5607R

 Make & Model:
 MERCEDES-BENZ E250, 1.8 (A)
 Engine No:
 27492030419245

 Reg. Date:
 04/11/2015 (Man. Year: 2015)
 Chassis No:
 WDD2120362B208756

Colour: Metallic Silver Odometer: 44246 km

Engine Capacity: 1991 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40Z R18 Rear Tyre Size: 265/35Z R18
Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		13,470.00	4,982.94	8,487.06	63.01
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,130.00	880.00	1,250.00	58.69
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	15.600.00	5.862.94	9,737.06	62.42

INSPECTION

Date of Assignment: 06/10/2020

Date Inspected: 06/10/2020 Inspected At: Poon Siang Seow (HQ)

160 Sin Ming Drive, #05-13 Sin Ming

AutoCity

Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Page 2 of 3 Adjuster Report

REPAIR DETAILS

Reference Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Oct 2020) Parts: 143 MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0) Labour: (Price-denominated Standard List) Repairer's Print Code: (Unsubmitted, no print-code for SKW5607R) These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity: numbers with the END OF ESTIMATES marker on the last estimate page Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER	Torn	1,866.00 F	*1,435.00 FL	
2	1		*FRONT BUMPER INNER PART	Cracked	148.00 F	*148.00 FL	
3	1		*FRONT BUMPER SENSOR (2PCS)	Missing (1Pc Only)	626.00 F	*282.20 FL	
4	1		*HEAD LAMP LEFT	Broken	5,757.00 F	*3,382.40 FL	
5	1		*FRONT FENDER LEFT	Repair	1,189.00 F	*-FL	
6	1		*FRONT FENDER INNER GARNISH	Serviceable	235.00 F	*- FL	
7	1		*FRONT FENDER BADGE EDITION	Necessary	124.00 F	*124.00 FL	
8	1		*WHEEL RIM	Repair	2,910.00 F	*- FL	
9	1		*FRONT TYRES	Serviceable	350.00 F	*-FL	
10	1		*FRONT WIPER TANK	Dented	265.00 F	*165.00 FL	
F=Franchise part. L=ListItemDisc.							
				Sub Total (S\$)	13,470.00	5,536.60	
			- List Item Discount on L	. Items 0.00/10.00% (S\$) _	0.00	553.66	
				Total Parts (S\$)	13,470.00	4,982.94	
Report was unsubmitted during this print-out.							

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen... 19/10/2020

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	RUST PROOFING	New	50.00	0.00
2	PROGRAMMING AND RESETTING OF THE SYSTEM	New	300.00	0.00
3	PANEL BEATING	New	800.00	400.00
4	SPRAY PAINTING	New	980.00	480.00
	Gross La	2,130.00	880.00	
	Report was unsubmitted du	ring this print-out.		

< END OF ESTIMATES >