

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Oct 2020 Edit Reg		07 Oct 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	JIJOSH GURUDASAN, ID: S8673818Z		
Main Claimant:	-		
Vehicle Reg. No.:	SJU5419P	Date of Loss:	04/10/2020 00:00 - :59 [129 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3939148594SG	Policy/Cover Note No.:	1800126440 (Comprehensive)
Vehicle Reg. No. (Insured):	SLJ120S	Policy No. (Claimant):	
		Excess:	
Repairer:	Han Car Repairs (HQ) BLK 1001 BUKIT MERAH LANE 3 #01-49 ALEXANDRA VILLAGE, 159718 Alexandra - Tel: 62710275		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Yong, Joanne] Joanne-LF.yong@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 15/10/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

*SJU5419P (3939148594SG)

[SLJ120S]

TP

-

Oct 4 2020 12:00AM

[JIJOSH GURUDASAN]

Han Car Repairs

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View
[View in Browser](#)

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	07/10/20 15:38	Video - Accident	Load MP4	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/10/20 20:17	Odometer Reading	Load JPG	☒
2	07/10/20 20:17	Chassis Number	Load JPG	☒
3	07/10/20 20:17	General View	Load JPG	☒
4	07/10/20 20:17	General View	Load JPG	☒
5	07/10/20 20:17	General View	Load JPG	☒
6	07/10/20 20:17	General View	Load JPG	☒
7	07/10/20 20:17	General View	Load JPG	☒
8	07/10/20 20:17	General View	Load JPG	☒
9	07/10/20 20:17	General View	Load JPG	☒
10	07/10/20 20:17	General View	Load JPG	☒
11	07/10/20 20:17	General View	Load JPG	☒
12	07/10/20 20:17	General View	Load JPG	☒
13	07/10/20 20:17	General View	Load JPG	☒
14	07/10/20 20:17	General View	Load JPG	☒
15	07/10/20 20:17	General View	Load JPG	☒
16	07/10/20 20:17	General View	Load JPG	☒
17	07/10/20 20:17	General View	Load JPG	☒
18	07/10/20 20:17	General View	Load JPG	☒
19	07/10/20 20:17	General View	Load JPG	☒
20	07/10/20 20:17	General View	Load JPG	☒
21	07/10/20 20:17	General View	Load JPG	☒
22	07/10/20 20:17	General View	Load JPG	☒
23	07/10/20 20:17	General View	Load JPG	☒
24	07/10/20 20:17	General View	Load JPG	☒
25	07/10/20 20:17	General View	Load JPG	☒
26	07/10/20 20:17	General View	Load JPG	☒
27	07/10/20 20:17	General View	Load JPG	☒
28	07/10/20 20:17	General View	Load JPG	☒
29	07/10/20 20:17	General View	Load JPG	☒
30	07/10/20 20:17	General View	Load JPG	☒
31	07/10/20 20:17	General View	Load JPG	☒
32	07/10/20 20:17	General View	Load JPG	☒

Video			1 per page ▾	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
33	07/10/20 20:18	General View	 Load JPG	☒
34	07/10/20 20:18	General View	 Load JPG	☒
35	07/10/20 20:18	General View	 Load JPG	☒
36	07/10/20 20:18	General View	 Load JPG	☒
37	07/10/20 20:18	General View	 Load JPG	☒
38	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
39	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
40	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
41	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
42	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
43	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
44	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
45	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
46	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
47	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
48	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
49	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
50	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
51	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
52	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
53	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
54	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
55	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
56	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
57	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
58	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
59	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
60	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
61	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
62	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
63	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
64	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
65	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
66	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
67	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
68	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
69	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
70	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
71	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
72	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
73	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
74	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
75	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
76	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
77	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
78	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
79	14/10/20 14:31	Photographs of Damaged Parts	 Load JPG	☒
80	14/10/20 14:32	Reinspection Photo	Load JPG	☒

Video			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
81	14/10/20 14:32	Reinspection Photo		Load JPG ✓
82	14/10/20 14:32	Reinspection Photo		Load JPG ✓
83	14/10/20 14:32	Reinspection Photo		Load JPG ✓
84	14/10/20 14:32	Reinspection Photo		Load JPG ✓
85	14/10/20 14:32	Reinspection Photo		Load JPG ✓
86	14/10/20 14:32	Reinspection Photo		Load JPG ✓
87	14/10/20 14:32	Reinspection Photo		Load JPG ✓
88	14/10/20 14:32	Reinspection Photo		Load JPG ✓
89	14/10/20 14:32	Reinspection Photo		Load JPG ✓
90	14/10/20 14:32	Reinspection Photo		Load JPG ✓
91	14/10/20 14:32	Reinspection Photo		Load JPG ✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	08/10/20 10:27	TP GIA REPORT		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	07/10/20 15:37	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG20010762/R1VD3S2**Date:** 15/10/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800126440
Claimant Vehicle No :	SJU5419P	Insured Vehicle No :	SLJ120S
Date of Loss:	04/10/2020	Nature of Claim:	TP
		Claim No:	3939148594SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU5419P	Engine No:	L15A5207746
Make & Model:	HONDA AIRWAVE, 1.5 M (A)	Chassis No:	GJ11306376
Reg. Date:	15/12/2009 (Man. Year: 2008)	Odometer:	167427 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	07/10/2020	
Date Inspected:	07/10/2020 Inspected At:	Han Car Repairs (HQ) BLK 1001 BUKIT MERAH LANE 3 #01-49 ALEXANDRA VILLAGE Singapore 159718
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER LH	Cracked	0.00 F	*- F
4	1		*REAR END PANEL	Repair	0.00 F	*- F
5	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
6	1		*TAILGATE	Repair	0.00 F	*- F
7	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >