

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG20010763/GPA3Q2  
**Date:** 27/06/2021**REFERENCE**

|                              |                                      |                             |            |                        |
|------------------------------|--------------------------------------|-----------------------------|------------|------------------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2100019520 |                        |
| <b>Claimant Vehicle No :</b> | SML159J                              | <b>Insured Vehicle No :</b> | SGU2987X   |                        |
| Date of Loss:                | 30/09/2020                           | Nature of Claim:            | TP         | Claim No: 0940739924SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SML159J</b>                    |             |                   |
| Make & Model:               | TOYOTA HARRIER, 2.0 G GRADE (A)   | Engine No:  | 8ARZ158120        |
| Reg. Date:                  | 30/04/2019 (Man. Year: 2019)      | Chassis No: | JTEKB3GH70J004486 |
| Colour:                     | White                             | Odometer:   | 16245 km          |
| Engine Capacity:            | 1998 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 235/55 R18       | Rear Tyre Size:  | 235/55 R18       |
| Front Left Side:  | Bridgestone 6 mm | Rear Left Side:  | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 3,325.09          | 2,064.67          | 1,260.42          | 37.91         |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 1,060.00          | 900.00            | 160.00            | 15.09         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>4,385.09</b>   | <b>2,964.67</b>   | <b>1,420.42</b>   | <b>32.39</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>306.96</b>     | <b>207.53</b>     | <b>99.43</b>      | <b>32.39</b>  |

|                                                 |                 |                 |                 |              |
|-------------------------------------------------|-----------------|-----------------|-----------------|--------------|
| <b>Nett Amount (S\$)</b>                        | <b>4,692.05</b> | <b>3,172.20</b> | <b>1,519.85</b> | <b>32.39</b> |
| <b>+ Car Rental (5.5 x S\$160.00/day) (S\$)</b> |                 | 880.00          |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                 | 2.00            |                 |              |
| <b>Nett Liability (S\$)</b>                     |                 | <b>4,054.20</b> |                 |              |
| <b>Global Sum Settlement (S\$)</b>              |                 | <b>4,050.00</b> |                 |              |

INSPECTION

Date of Assignment: 06/10/2020

Date Inspected: 07/10/2020

Estimated Period of Repair: 4.0 days

Inspected At:

VIN'S MOTOR PTE LTD  
 Sin Ming AutoCity,, 160 Sin Ming Drive #03-03  
 Singapore 575722

**Adjuster:** XING GUO QIANG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                        | Condition     | Repairer's | Amount     |
|-----|-----|----------|------------------------------------|---------------|------------|------------|
| 1   | 1   |          | *REAR BUMPER                       | Broken        | 904.00 FL  | *904.00 FL |
| 2   | 2   |          | *REAR BUMPER PARKING SENSOR        | Damaged       | 743.60 FL  | *743.60 FL |
| 3   | 1   |          | *REAR BUMPER LH REFLECTOR          | Not Necessary | 56.90 FL   | *- FL      |
| 4   | 1   |          | *REAR BUMPER RH REFLECTOR          | Not Necessary | 56.90 FL   | *- FL      |
| 5   | 2   |          | *REAR BUMPER SIDE RETAINER         | Not Necessary | 184.66 FL  | *- FL      |
| 6   | 1   |          | *REAR BUMPER SPONGE                | Cracked       | 117.20 FL  | *117.20 FL |
| 7   | 1   |          | *REAR BUMPER ANTENNA SENSOR        | Damaged       | 107.00 FL  | *72.00 FL  |
| 8   | 1   |          | *REAR BUMPER BUZZIE SENSOR         | Not Necessary | 159.50 FL  | *- FL      |
| 9   | 1   |          | *REAR END PANEL                    | Repair        | 715.30 FL  | *- FL      |
| 10  | 1   |          | *REAR END PANEL PERFORMANCE DAMPER | Bent          | 922.30 FL  | *450.00 FL |
| 11  | 1   |          | *REAR BUMPER LOWER SPOILER         | Deformed      | 466.10 FL  | *466.10 FL |

F=Franchise part. L=ListItemDisc.

|                                                          |                 |                 |
|----------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>4,433.46</b> | <b>2,752.90</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$)</b> | 1,108.37        | 688.23          |
| <b>Total Parts (\$)</b>                                  | <b>3,325.09</b> | <b>2,064.67</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars            | Lab.Type | Repairer's      | Amount        |
|--------------------------------|------------------------|----------|-----------------|---------------|
| <u>Labour Items</u>            |                        |          |                 |               |
| 1                              | TO REPAIR REAR DAMAGES | New      | 480.00          | 400.00        |
| 2                              | TO SPRAY PAINTING      | New      | 580.00          | 500.00        |
| <b>Gross Labour Cost (S\$)</b> |                        |          | <b>1,060.00</b> | <b>900.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >