

Our Ref : TP/102020/4543
Accident date : 30/9/2020
Your Ref : SGU2987X

MOTOR CLAIM DEPARTMENT
AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building
78 Shenton Way #07-16
Singapore 079120

ESTIMATE COST OF REPAIRS TO

Vehicle No. : SML159J
Model : TOYOTA HARRIER G GRADE

1	pc	Rear bumper	/ BR		\$	904.00
2	pcs	Rear bumper parking sensor	@ \$371.80	?	\$	743.60
1	pc	Rear bumper LH reflector	X		\$	56.90
1	pc	Rear bumper RH reflector	X		\$	56.90
2	pcs	Rear bumper side retainer	@ \$92.33	X	\$	184.66
1	pc	Rear bumper sponge	/ CA		\$	117.20
1	pc	Rear bumper antenna sensor			\$	107.00
1	pc	Rear bumper buzzie sensor	?		\$	159.50
1	pc	Rear end panel	Repair X		\$	715.30
1	pc	Rear end panel performance damper	/ BR		\$	922.30
					\$	3,967.36
Less 25%					\$	(991.84)
					\$	2,975.52

To repair rear damages
To spray painting

\$ 480.00 400
\$ 580.00 500
\$ 4,035.52

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Invoice No.:
Date : 6/10/2020
Acknowledged by Repairer
Signature:
Date:

4 Days
Part by part
before part photos.
Guo Qiang - 8288282
07/10/2020

VIN'S MOTOR PTE LTD