



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6889Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	I40V3 BUMPER W LIP & FOG	BROKEN	1,052.20	1,052.20
10	HYUNDAI BUMPER COVER CLIP	NOT NECESSARY	22.00	-
1	I40V3 GRILLE ASSY-RADIATO	BROKEN	1,480.00	1,480.00
1	I40V3 SYMBOL MARK-H	NECESSARY	39.50	39.50
	LESS 20% DISCOUNT		-518.74	-514.34
			2,074.96	2,057.36
<u>NETT ITEMS</u>				
1	NO PLATE(S) WITH TRIM COV (N)	CUT	55.00	55.00
	LESS 10% DISCOUNT		-5.50	-5.50
			49.50	49.50
<u>LABOUR</u>				
	PANEL BEATING.		350.00	280.00
	SPRAYPAINT ON AFFECTED AREA.		250.00	200.00
			600.00	480.00
GRAND TOTAL			2,724.46	2,586.86
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,050.00

Report Ref No. NS/INC20010765/Evd3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.