

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20010775/EBA3Q2

**Date:** 13/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800152156

**Claimant**  
**Vehicle No :** SH6451A **Insured Vehicle No :** SMG8340A

Date of Loss: 06/10/2020 Nature of Claim: TP Claim No: 1870351062SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SH6451A</b>	Engine No:	G4LEKU397225
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU186456
Reg. Date:	22/10/2019 (Man. Year: 2019)	Odometer:	131929 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodyear 4 mm	Rear Left Side:	Goodyear 4 mm
Front Right Side:	Goodyear 4 mm	Rear Right Side:	Goodyear 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,271.70	1,271.70	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	780.00	550.00	230.00	29.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>2,051.70</b>	<b>1,821.70</b>	<b>230.00</b>	<b>11.21</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	143.62	127.52	16.10	11.21
<b>Nett Amount (\$\$)</b>	<b>2,195.32</b>	<b>1,949.22</b>	<b>246.10</b>	<b>11.21</b>
<b>+ Car Rental (2.0 x S\$125.19/day) (\$\$)</b>		250.38		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>2,201.60</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>2,200.00</b>		

### INSPECTION

Date of Assignment: 07/10/2020

Date Inspected: 07/10/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd  
(Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 2.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER -RR BUMPER	Broken	459.40 FL	*459.40 FL
2	1		*MOULDING ASSY-R	Deformed	451.25 FL	*451.25 FL
3	1		*CAP-RR HOOK	Cut	98.80 FL	*98.80 FL
4	1		*PROTECTOR MAT	Necessary	50.00 FS	*50.00 FS
5	10		*HYUNDAI BUMPER COVER CLIP	Necessary	22.00 FL	*22.00 FL
6	1		*HYUNDAI REVERSE SENSOR AS	Broken	135.70 FS	*135.70 FS
7	1		*BEAM -RR BUMPER	Broken	294.80 FL	*294.80 FL
8	1		*NO PLATE	Broken	25.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>1,536.95</b>	<b>1,536.95</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	265.25	265.25
<b>Total Parts (S\$)</b>	<b>1,271.70</b>	<b>1,271.70</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	320.00
2	SPRAYPAINT CHARGE	New	300.00	200.00
3	REMOVE/REFIX REVERSE SENSOR ASSY	New	80.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>780.00</b>	<b>550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >