Adjuster Report Page 1 of 6

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI20010776/KTF3E2

Date: 30/10/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MV007263

Claimant Vehicle No: GBE738E

Date of Loss: 05/10/2020 Nature of Claim: TP Claim No: M2004936

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD9500Z

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2C22903

Reg. Date: 31/05/2019 (Man. Year: 2018) Chassis No: JTDKB3FU403080996

Colour: Metallic Pearl White/Red Odometer: 179706 km

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: Sailun 9 mm Rear Left Side: Sailun 9 mm
Front Right Side: Sailun 9 mm Rear Right Side: Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,474.70	839.17	5,635.53	87.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,460.00	480.00	2,980.00	86.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,934.70	1,319.17	8,615.53	86.72
+ GST 7.00/7.00% (S\$)	695.43	92.34	603.09	86.72
Nett Amount (S\$)	10,630.13	1,411.51	9,218.62	86.72

INSPECTION

Date of Assignment: 07/10/2020

Date Inspected: 06/10/2020 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo

Kio)

2, Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: DENISE TAY KWEE CHENG

Adjuster Report Page 2 of 6

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 6

Different 1 cents -Finalise confirm amount: \$1319.18

Adjuster Report Page 4 of 6

REPAIR DETAILS

Reference					
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2020)			
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)			
Labour:	Repairer's	(Price-denominated Standard List)			
Print Code:	Print Code: (Unsubmitted, no print-code for SHD9500Z)				
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page				
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.					

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*COVER,REAR BUMPER	Buckled	442.60 FL	. -	*442.60 FL
2	1		*REINFORCEMENT SUB-ASSY,REAR BUMPER	Serviceable	332.70 FL	. -	*- FL
3	1		*COVER REAR BUMPER LOWER	Serviceable	15.40 FL	_	*- FL
4	1		*GUARD REAR BUMPER,CENTER	Dented/Cut	576.30 FL		*576.30 FL
5	1		*RETAINER,REAR BUMPER SIDE,LH	Serviceable	116.50 FL		*-FL
6	1		*PANEL SUB-ASSY,BACK DOOR	Repair	1,147.80 FL		*- FL
7	1		*GARNISH SUB-ASSY,BACK DOOR,OUTSIDE	Serviceable	925.60 FL		*-FL
8	1		*WEATHERSTRIP,BACK DOOR	Serviceable	372.30 FL		*-FL
9	1		*PANEL SUB-ASSY,BODY LOWER BACK	Repair	650.30 FL		*- FL
10	1		*LENS AND BODY,REAR LAMP,LH	Serviceable	502.00 FL		*-FL
11	1		*LENS & BODY,REAR COMBINATION LAMP,LH		443.30 FL		*-FL
12	1		*FILLER,REAR BUMPER EXTENSION,LH	Serviceable	123.70 FL		*-FL
13	1		*COVER,REAR FLOOR	Serviceable	229.90 FL		*-FL
14	1		*COVER FLOOR UNDER,NO 2	Serviceable	241.90 FL		*-FL
15	1		*MOULDING,BACK DOOR OUTSIDE GARNISH,LOWER LH	Serviceable	56.50 FL		*- FL
16	1		*SET PARKING AID	Serviceable	700.00 FS		*-FS
17	1		*SET REAR BUMPER CLIP	Necessary	90.00 FS		*75.00 FS
18	1		*REAR TAILGATE TOYOTA LOGO	Not Necessary	47.90 FS	-	*-FS
19	1		*REAR TAILGATE WORDING PRIUS	Not Necessary	54.60 FS	-	*-FS
20	1		*REAR TAILGATE WORDING HYBRID	Not Necessary	54.60 FS	-	*-FS
21	1		*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	-	*-FS
22	1		*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	-	*-FS
23	1		*REAR BUMPER RETAINER CLIP	Not Necessary	65.00 FS	-	*-FS
24	1		*SET TAILLAMP CLIP	Not Necessary	60.00 FS	-	*-FS
25	1		*REAR LICENCE PLATE WITH HOLDER	Serviceable	130.00 FS	-	*- FS
26	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	-	*-FS
27	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	-	*-FS
28	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	-	*-FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 6

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
				Sub Total (S\$)	8,018.90	1,093.90	
				- List Item Discount on L Items 25.00/25.00% (S\$)	1,544.20	254.73	
				Total Parts (S\$)	6,474.70		839.17
				Report was unsubmitted during this print-out.			

Adjuster Report Page 6 of 6

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	<u>Labour Items</u>							
1	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00				
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	220.00				
3	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00				
4	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00				
5	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	1,200.00	200.00				
6	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00				
7	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00				
	Gross Labou	ır Cost (S\$)	3,460.00	480.00				
	Report was unsubmitted during	this print-out.						

< END OF ESTIMATES >